0005

5-23-89 7070

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Ok RVS

inspection report

Permit No. ACT/007/013

Inspection Date 4/28/89 & 5/3/89

Permittee/Operator Name Kaiser Coal Corporation

Business Address P.O. Box 1107

City Raton State NM Zip 87740

Mine Horse Cyn ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut

Company Official(s) John M Palfy (Representing Kaiser)

State Official(s) Bill Malencik

Time of inspection 4/28 9:00 ☒ a.m. ☐ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
5/3 10:00 ☒ a.m. ☐ p.m. to 5:00 ☐ a.m. ☒ p.m.

Date of last inspection 1/5/89 Weather conditions Clear/Warm/Windy

Acreage 1917 ☐ Permitted 50 ☐ Disturbed ☐ Regraded ☐ Seeded 50 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date 4/28 & 5/3-89

Please number comments to correspond with topics on previous page.

General Comments: John Palfy, North American Consultants, Inc. representing Kaiser Coal Corp accompanied the undersigned on the 05/3/89 inspection. Mine records for the Horse Cyn operation have been moved from the Sunnyside Mine Office and are currently on file at Price. The records are available through Mr Palfy.

Permit: The mine is in an inactive status. Intermountain Power is a prospective purchaser of the Horse Cyn Mine.

Sediment Ponds: Sediment ponds were checked and elevations from the decant device to current sediment level were recorded in the field book. All ponds appear stable. Only two out of the nine pond showed any evidence that water had been retained in the pond this spring. At the time of this inspection all ponds were dry.

Other Sediment Control: Silt fences, straw bales, & berms were checked. With the natural revegetation that has & is currently taking place the volume of runoff and sediment has been reduced as a result of mine inactivity.

Surface & Groundwater Monitoring: Water monitoring records were

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date 4/28 & 5/3-89

Please number comments to correspond with topics on previous page.

checked and no problems were noted.

Revegetation: The revegetation by the west portals and by the water tank was observed. The portal seeding has a good start, especially the alfalfa. The water tank area may need retreatment. However, the retreatment, if needed, would best be done when the water tank is removed in order to avoid redisturbance.

Roads All roads to the mine site and in the mine site were in good condition

Other Comments: The buildings at the mine site are continually being subjected to breakins and vandalism.

Copy of report mailed to { Kaiser Coal Corp. / SLC FOR: ~~OSM/DOGM~~ Brian Smith/OSM, Joe Helfrich/DOGM

Copy of report ~~given to~~ filed PFO

Inspector's signature Jim J. Smalenick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

5/5/89.