UTAH
NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jh RUS

inspection report

Permit No. ACT/007/013
Inspection Date Aug. 16, 1989

Permittee/Operator Name KAISER COAL CORP.
Business Address P.O. BOX 1107
City RATON State NM. Zip 87740
Mine HORSE CANYON ☐ Surface ☒ Underground ☐ Other
County CARBON State UT
Company Official(s) NONE
State Official(s) BILL WAKMACK
Time of inspection 8:00 ☒ a.m. ☐ p.m. to 10:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection July 26, 1989 Weather conditions PARTLY CLOUDY & COOL
Acreage 1917 ☐ Permitted 50 ☐ Disturbed ☐ Regraded ☐ Seeded 50 ☐ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☒	☐	☐	☒
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date Aug. 16, 1989

Please number comments to correspond with topics on previous page.

GENERAL: THIS PARTIAL INSPECTION WAS CONDUCTED WITHOUT REPRESENTATION FROM KAISER COAL CORP. GROUND CONDITIONS WERE MOIST, HOWEVER, IT DID NOT APPEAR AS THOUGH ANY MEASURABLE PRECIPITATION HAD RECENTLY OCCURRED. SEDIMENTATION PONDS DID NOT CONTAIN WATER ALTHOUGH SEVERAL WERE "WET." STATE NOV # 89-26-19-1 (DATED 7/27/89) WAS TERMINATED ON AUGUST 10, 1989 BY A DIVISION REPRESENTATIVE.

4d. OTHER SED CONTROLS: RECENTLY INSTALLED AND/OR REPAIRED SILT FENCES WERE INSPECTED & FOUND TO BE FUNCTIONAL & ADEQUATE.

4e. SURFACE & GROUNDWATER MONITORING: SOUTH FORK (RIGHT FORK) OF HORSE CANYON WAS OBSERVED FLOWING. MEASUREMENT TAKEN DURING THE INSPECTION INDICATED 1.6 gpm

Copy of report mailed to JOE HELFRICH (DOGM), BRIAN SMITH (OSM), JOHN PALEY (KCC)

Copy of report given to PFO

Inspector's signature William A. Warnock 8/16/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE