9-20-89
7070

0013

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gdh KVS

inspection report

Permit No. ACT/007/013
Inspection Date SEPT. 19, 1989

Permittee/Operator Name KAISER COAL CORPORATION
Business Address P.O. BOX 1107
City RATON State NEW MEXICO Zip 87740
Mine HORSE CANYON ☐ Surface ☑ Underground ☐ Other
County CARBON State UTAH
Company Official(s) NONE
State Official(s) PAM Grubaugh-Littig
Time of inspection 8:10 ☑ a.m. ☐ p.m. to 9:30 ☑ a.m. ☐ p.m. ☑ Partial ☐ Complete
Date of last inspection AUG. 16, 1989 Weather conditions SUNNY and WARM
Acreage ☐ Permitted 50 ☑ Disturbed ☐ Regraded ☐ Seeded 50 ☑ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☑	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☑	☐	☐	☐
d Other sediment control measures	☑	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☑	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date SEPT. 19, 1989

Please number comments to correspond with topics on previous page.

4c. Sedimentation ponds did not contain any water but were "damp". The entire site had received a small amount of precipitation during the night.

4d. Silt fences were observed and functional.

2. Signs indicating the perimeter are posted. The topsoil sign was noted in the topsoil pile. All of the signs are clear and legible.

8. The site has generally good housekeeping. No junk was seen on site.

Copy of report mailed to John Palfy (Kaiser Coal Corp); John Cathmann (OSM)

Copy of report given to Joe Helfrich (DOGM), PFO

Inspector's signature Wanda Burbaugh-Lithig No. 29

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE