

0003

Document Information Form

Mine Number: C/007/013

File Name: Incoming

To: DOGM

From:

Person N/A

Company N/A

Date Sent: N/A

Explanation:

REFUSE PILE INSPECTION REPORT

cc:

File in: C/007, 013, Incoming

Refer to:

- Confidential
- Shelf
- Expandable

Date: _____ For additional information

REFUSE PILE INSPECTION REPORT

02/007/013
File Reports
QUARTER 1/90

MSHA SITE 1211-UT-09-0018

HORSE CANYON

(Hillside Refuse Pile)

ITEM	REMARKS
(1) Potential Safety Hazards	No Safety Hazards Noted.
(2) Slope Stability	Slopes approximately 1:1; however, they appear stable. No recent erosion evident.
(3) Removal of Topsoil and Organics	Topsoil or Organic Removal is Unknown. Top of Pile about 60% Vegetated. Slopes are about 30% Vegetated.
(4) Construction and Maintenance Performance Standards	No Erosion Controls Evident. Pile Appears Stable. Small Gully from Top near West End.
(5) Recommendations	Monitor Erosion or Migration of Material. Implement Controls if Necessary.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No. 0003 Date _____
In C/ 007, 013, Incoming
For additional information



REFUSE PILE INSPECTION REPORT

MSHA SITE - N/A

HORSE CANYON

QUARTER 1/90

(Road Junction Refuse Pile)

<u>ITEM</u>	<u>REMARKS</u>
(1) Potential Safety Hazards	<u>No Safety Hazards Noted.</u> <u></u> <u></u>
(2) Slope Stability	<u>Slopes Appear Stable. No Recent</u> <u>Erosion Noted. South Slope approx.</u> <u>1:1 - Extends to Wash.</u>
(3) Removal of Topsoil and Organics	<u>Pile Partially Vegetated - 20%-30%.</u> <u>Removal of Topsoil and Organics is</u> <u>Unknown. Small Topsoil Pile to NW.</u>
(4) Construction and Maintenance Performance Standards	<u>No I.D. Sign Noted. No Erosion</u> <u>Controls Below Pile; however, a</u> <u>Drainage Control Plan has been Submitted.</u>
(5) Recommendations	<u>Monitor for Erosion or Migration of</u> <u>Material. Implement Drainage Control</u> <u>Plan upon Approval.</u>

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.

