0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/013
Inspection Date 3/15/90

Permittee/Operator Name KAISER COAL CORP
Business Address P.O. BOX 1107 RATON, NEW MEXICO 87740
City RATON State NEW MEXICO Zip 87740
Mine HORSE CANYON ☐ Surface ☒ Underground ☐ Other
County CARBON State UTAH
Company Official(s) JOHN PALFY, MEL COONROD
State Official(s) TOM MUNSON, JESS KELLEY
Time of inspection 1:30 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection 12/6+8, 1989 Weather conditions CLOUDY
Acreage ☐ Permitted 50 ☒ Disturbed ☐ Regraded ☐ Seeded 50 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☒
– Diversions	☒	☐	☐	☐
b Sediment ponds and impoundments	☒	☐	☐	☒
– Other sediment control measures	☒	☐	☐	☐
c Surface and groundwater monitoring	☒	☐	☐	☒
– Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☒
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
– Construction	☒	☐	☐	☐
– Drainage controls	☒	☐	☐	☐
– Surfacing	☒	☐	☐	☐
– Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date 3/15/90

Please number comments to correspond with topics on previous page.

4a All diversions were inspected and no areas of concern were noted

b) All impoundments were dry. ~~[illegible]~~

c) The surface and groundwater monitoring was current for 1989 and the first quarter data for 1990 was not available at the time of inspection. The operator has still adequate time to submit the 1st quarter data for 1990.

11.) The reclamation of the pond embankments was contingent on the receipt of soil data from the borrow area and the pond bottoms. Those samples have been submitted to the lab and the results of the lab work had not been

Copy of report mailed to JOHN PALFY - KAISER COAL COMPANY

Copy of report given to

Inspector's signature Thomas Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date 3/15/90

Please number comments to correspond with topics on previous page.

11) cont) received by the operator by 3/15/90. When the data are received they will be reviewed by the division.

Additional information for the Coarse Refuse area drainage plan is still pending and has not been received by the division to date. Deadlines for both issues are towards the end of April.

Overall, the site looked in good repair and all sediment control devices (i.e. silt fences were in good repair). No runoff was noted from snowmelt, although patches of snow still were apparent. The ground was ~~[illegible]~~ still frozen due to the recent cold weather and below freezing temperatures.

Copy of report mailed to JOHN PALEY - KAISER COAL COMPANY

Copy of report given to JOE HELFRICH DOGM, BRIAN SMITH OSM

Inspector's signature Thomas Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE