

0007



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: September 7, 1990
.1 hour

Permittee and/or Operators Name: Intermountain Power Agency
Business Address: Rm 1164, 111 North Hope St, Los Angeles, CA
Mine Name: Horse Canyon Permit Number: ACT/007/013
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official(s): Rad Orell, Charles Sandberg
State Official(s): Bill Malencik,
Partial: Complete: Date of Last Inspection
Weather Conditions: Clear and Sunny
Acreage: Permitted Disturbed Regraded Seeded Bonded
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
<u>1. PERMITS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>2. SIGNS AND MARKERS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>3. TOPSOIL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>4. HYDROLOGIC BALANCE:</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>a. STREAM CHANNEL DIVERSIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>b. DIVERSIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>c. SEDIMENT PONDS AND IMPOUNDMENTS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>d. OTHER SEDIMENT CONTROL MEASURES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>e. SURFACE AND GROUNDWATER MONITORING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>f. EFFLUENT LIMITATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>5. EXPLOSIVES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>7. COAL PROCESSING WASTE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>8. NONCOAL WASTE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>9. PROTECTION OF FISH, WILDLIFE AND</u>				
<u>RELATED ENVIRONMENTAL VALUES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>10. SLIDES AND OTHER DAMAGE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>11. CONTEMPORANEOUS RECLAMATION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>12. BACKFILLING AND GRADING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>13. REVEGETATION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>14. SUBSIDENCE CONTROL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>15. CESSATION OF OPERATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>16. ROADS</u>				
<u>a. CONSTRUCTION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>b. DRAINAGE CONTROLS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>c. SURFACING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>d. MAINTENANCE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>17. OTHER TRANSPORTATION FACILITIES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>18. SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>

INSPECTION REPORT
(continuation sheet)

DATE OF INSPECTION September 7, 1990

Page 2 of 2

On September 7, 1990, an aerial inspection of this site was conducted by the referenced State and Federal officials. No violations were observed.

Photographs (slides), were taken and are available at the Division of Oil, Gas and Mining, Salt Lake Office as well as the Office of Surface Mining, Albuquerque Field Office.

Copy of this Report:

Mailed/filed to: John Kathmann (OSM) Joe Helfrich (DOGM)

Filed to: Price Field Office

Inspectors Signature *Jim J. Chalovich* Date: September 11, 1990