UTAH
NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

page gch



# inspection report

Permit No. ACT/007/013
Inspection Date 11/16/90

Permittee/Operator Name Intermountain Power Agency
Business Address Room 1164, 111 North Hope St.
City Los Angeles State CA Zip 90012
Mine Horse Canyon Mine ☐ Surface ☒ Underground ☐ Other
County Carbon State UT
Company Official(s) Paul Clark (T&B)
State Official(s) Susan White
Time of inspection 1:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection 10/11/90 Weather conditions Cool & high clouds
Acreage ☐ Permitted 63.6 ☒ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded
Enforcement Action NOV 35-02-01

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ✓ | | | ✓ |
| 2. Signs and markers | ✓ | | | ✓ |
| 3. Topsoil | ✓ | | | |
| 4. Hydrologic balance | | | | |
| a. Stream channel diversions | ✓ | | | |
| b. Diversions | ✓ | | | ✓ |
| c. Sediment ponds and impoundments | ✓ | | | ✓ |
| d. Other sediment control measures | ✓ | | | ✓ |
| e. Surface and groundwater monitoring | ✓ | | | ✓ |
| f. Effluent limitations | ✓ | | | |
| 5. Explosives | | | ✓ | |
| 6. Development waste and spoil disposal | ✓ | | | |
| 7. Coal processing waste | ✓ | | | |
| 8. Noncoal waste | ✓ | | | |
| 9. Protection of fish, wildlife, and related environmental values | ✓ | | | |
| 10. Slides and other damage | | | ✓ | |
| 11. Contemporaneous reclamation | ✓ | | | ✓ |
| 12. Backfilling and grading | ✓ | | | ✓ |
| 13. Revegetation | ✓ | | | |
| 14. Subsidence control | ✓ | | | |
| 15. Cessation of operations | | | | |
| 16. Roads | | | | |
| — Construction | ✓ | | | |
| — Drainage controls | ✓ | | | |
| — Surfacing | ✓ | | | |
| — Maintenance | ✓ | | | |
| 17. Other transportation facilities | ✓ | | | |
| 18. Support facilities and utility installations | ✓ | | | |

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date 11/16/90

Please number comments to correspond with topics on previous page.

1. All permits, bonds and insurance were in order.
2. Temporary identification signs were readable but in disrepair. The operator will ~~change~~ replace the signs.
4. Silt fences were in good repair with the following maintance item: key in silt fence on south side of water tank and silt fence on north west side of refuse area is to be repaired.

The straw bales ~~of~~ in Horse Creek for interim sediment control were in place but required cleaning. The straw bales by Hillside Storage and PCB Storage require maintance.

The road into and by the old cyanatron bldg. will require the scale to be beefed-up prior to contractors leaving for the winter.

The area north of the scale house where the rail road ties are being stored require some type of sediment control.

The third sediment pond contained water

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date 11/16/90

Please number comments to correspond with topics on previous page.

otherwise all ponds were clean and dry.
The third quarter water monitoring data has been submitted and was in order.
11. The old conveyor had been taken down. Welders were in the process of breaking the structure into transportable size. The area south of the pump house on the north side of Horse Creek had been disturbed during the process of the conveyor demolition. The disturbance went outside of the disturbed area boundry markers. This resulted in a violation.
12. Material was being placed against the highwall near the south portals for backfill. It was noted to the company and DOGM engineer that wood was being placed in the fill.

Copy of report mailed to Dave Anderson (IPA); John Kathman (OSM)

Copy of report given to Joe Helfrich

Inspector's signature Susan M. White No. 35

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE