0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jah Page

inspection report

Permit No. ACT/007/013
Inspection Date 12/4/90

Permittee/Operator Name Intermountain Power Agency
Business Address Rm 11164, 111 North Hope St.
City Los Angeles State CA Zip 90012
Mine Horse Canyon ☐ Surface ☑ Underground ☐ Other
County Carbon State
Company Official(s) Paul Clark
State Official(s) Susan White Tom Emmet, Brian Smith (OSM)
Time of inspection 10:00 ☒ a.m. ☐ p.m. to 12:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 11/16/90 Weather conditions Fair and Cold
Acreage ☐ Permitted 63.0 ☒ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☑	☐	☐	☑
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation demolition	☑	☐	☐	☑
12. Backfilling and grading	☑	☐	☐	☑
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date 12/4/90

Please number comments to correspond with topics on previous page.

The site was inspected as to reclamation activities. Alot of progress has been made. All but one building (powder shack) remains to be demolished. The conveyor has almost all been hauled away. Work was progressing on the tipple.

Sediment control appeared in good condition. No precipitation has occured on site.

A berm was establish on the pad near the old Agnatron Bldg. Straw bales were replaced with silt fence near the old PCB Storage Bldg.

Material was being placed against the highwalls. RR ties had been dumped ~~against~~ in the fill and the contractor was removing them.

Copy of report mailed to David Anderson (IPA); John Kathman (OSM)

Copy of report given to Joe Helfrich

Inspector's signature Susan M. White No. 35

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE