



ENVIRONMENTAL INDUSTRIAL SERVICES

435-472-3814 • 800-641-2927 • FAX 435-472-8780 • eisec@sisna.com • 31 NORTH MAIN STREET HELPER, UTAH 84526

0057

June 26, 2001

Dave Darby
Division of Oil, Gas and Mining
P. O. Box 145801
Salt Lake City, UT 84114-5801

RE: Water Monitoring-Lila Canyon Mine

Dear Mr. Darby:

The purpose of this letter is to inform the Division of the recent water monitoring activities at sampling points: L-1-S, L-2-S, L-3-S, L-4-S, L-5-G, L-6-G, L-7-G, L-8-G, L-9-G, and L-10-G. Four attempts to visit all sites have been initiated since July, 24, 2000; July 24, 2000, November 28, 2000, February 7, 2001, and June 6, 2001. This information has been incorporated into the MRP.

The updated information in the MRP is accurate. There has been some confusion in the past as to the exact location of some of these sites. During July all ten monitoring points will be marked with a metal fence post that has a metal identification tag. This will eliminate any future confusion as to the exact location of these points.

Please contact me if you have any questions concerning this letter. Thank you for your past help and corporation on this matter.

Sincerely,

J. T. Paluso, P.E.
Senior Engineer-EIS

cc: Daron Haddock-DOGM
Jay Marshall-UEI

Copy Dave

J. T. Paluso
6/20/01