



Outgoing  
C0070013  
# 386102

	<b>Action Taken on Existing Citation Utah Coal Regulatory Program</b>	Action on Citation#: <b>10086</b>
	1594 West North Temple, Salt Lake City, UT 84114 Phone: (801) 538 - 5285 Fax: (801) 359-3940	Permit Number: <b>C0070013</b>
		Date Cit. Issued: <b>06/08/2011</b>
<input type="checkbox"/> MODIFICATION of <input checked="" type="checkbox"/> TERMINATION of <input type="checkbox"/> VACATION of		
<input checked="" type="checkbox"/> NOTICE OF VIOLATION <input type="checkbox"/> CESSATION ORDER (CO) <input type="checkbox"/> FAILURE TO ABATE CO		
Permittee Name: UTAHAMERICAN ENERGY INC	Inspector Number and ID: <b>46</b>	<b>PHESS</b>
Mine Name: HORSE CANYON MINE	Date and Time of Action: <b>06/29/2011</b>	<b>8:00 am</b>
Certified Return Receipt Number:	Date and Time of Service: <b>06/29/2011</b>	<b>8:05 am</b>
<i>In accordance with the provisions of the Utah Coal Mining and Reclamation Act, Utah Code Ann. § 40-10-1 et. seq. (Act), the above referenced Citation is:</i>		
<input type="checkbox"/> Modified as follows:		
<p style="text-align: center;">Reason for modification:</p>		
<input checked="" type="checkbox"/> <b>Terminated because:</b> The Permittee adequately addressed the three remedial actions listed on the NOV in the response received June 20, 2011. The surface facilities Plate 5-2, text in Chapter 5, pages 9, 13, and 16 and the reclamation cost estimate (Appendix 8-1) have been updated to include the demolition cost for the new rock dust tank system.		
<input type="checkbox"/> Vacated because:		
<b>R. Jay Marshall, General Manager</b> <small>(Print) Permittee Representative</small>	<b>PETE HESS</b> <small>(Print) DOGM Representative</small>	
<hr/> <small>Permittee Representative's Signature - Date</small>	 <small>DOGM Representative's Signature - Date</small>	
<b><u>Refer to the "Citation For Non-Compliance" for additional information</u></b>		