



# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

# Inspection Report

Permit Number:	C0070013
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, September 16, 2014
Start Date/Time:	9/16/2014 9:00:00 AM
End Date/Time:	9/16/2014 2:00:00 PM
Last Inspection:	Friday, September 19, 2014

Representatives Present During the Inspection:	
Company	Jay Marshall
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: Sunny, 80's

InspectionID Report Number: 3983

Accepted by: JHELFRIC  
10/7/2014

Permittee: **UTAHAMERICAN ENERGY INC**  
 Operator: **UTAHAMERICAN ENERGY INC**  
 Site: **HORSE CANYON MINE**  
 Address: **PO BOX 910, EAST CARBON UT 84520-0910**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

#### Current Acreages

5,992.07	<b>Total Permitted</b>
42.60	<b>Total Disturbed</b>
74.26	<b>Phase I</b>
74.26	<b>Phase II</b>
74.26	<b>Phase III</b>

#### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

#### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

#### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No coal was being ship during the inspection. There was a large stockpile of coal on the ground.

The permittee was constructing a truck turn-around for the loading of coal. This was approved by the Division. This should be completed within 2-4 weeks.

# Stephen J. Demczak

Digitally signed by Stephen J.  
Demczak  
DN: cn=Stephen J. Demczak, o, ou,  
email=stevedemczak@utah.gov, c=US  
Date: 2014.10.08 12:39:59 -06'00'

Inspector's Signature:

Steve Demczak,  
Inspector ID Number: 39

Date Tuesday, October 7, 2014



**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

## **2. Signs and Markers**

The Permittee had the proper identification signs in place. The ID signs were located at the point of access and included the name, address, telephone number, permit number and MSHA ID number. Disturbed area boundary, perimeter markers, and topsoil storage areas signs were correctly placed.

## **3. Topsoil**

Topsoil pile was stable. There were no signs of wind or water erosion. The permittee was adding additional topsoil to the pile from the new construction.

### **4.a Hydrologic Balance: Diversions**

I inspected the diversions and culverts throughout the property. The diversions and culverts were functioning as design. New diversions are in the process of construction due to the new truck turn-around and coal loading area.

### **4.b Hydrologic Balance: Sediment Ponds and Impoundments**

The sediment pond contain little to no water. There were no hazardous conditions and the embankments were stable.

### **4.c Hydrologic Balance: Other Sediment Control Measures**

Silt fences were functioning as design

## **8. Noncoal Waste**

The mine site was clear of non-coal waste material.

## **10. Slides and Other Damage**

No slides or damage were observed or reported.

### **16.b Roads: Drainage Controls**

Road drainage was functioning as design. The diversions will change once the truck turn-around is constructed.

## **17. Other Transportation Facilities**

The coal conveyor is schedule to be relocated in the near future.