



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070013
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, August 14, 2018
Start Date/Time:	8/14/2018 8:00:00 AM
End Date/Time:	8/14/2018 12:00:00 PM
Last Inspection:	Monday, July 16, 2018

Representatives Present During the Inspection:
OGM Karl Houskeeper

Inspector: Karl Houskeeper,

Weather: Smokey Skies, Temp.75 Deg. F.

InspectionID Report Number: 6215

Accepted by: DHADDOCK

8/20/2018

Permitee: **UTAHAMERICAN ENERGY INC**
 Operator: **UTAHAMERICAN ENERGY INC**
 Site: **HORSE CANYON MINE**
 Address: **PO BOX 910, EAST CARBON UT 84520-0910**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

4,664.32	Total Permitted
42.60	Total Disturbed
74.26	Phase I
74.26	Phase II
74.26	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The complete inspection begin the West Ridge Office, which is the main office for Utah American. This is where the paperwork is maintained for complete inspections. Karin Madsen was in the field. Done the paperwork and then done field inspection at Lila unattended.

Karl R. Houskeeper

Inspector's Signature:

Date Tuesday, August 14, 2018

Karl Houskeeper,
Inspector ID Number: 49



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

Division of Oil, Gas and Mining Permit C/007/0013 was issued for the Horse Canyon/Lila Canyon Mine on May 6, 2016 and expires on May 6, 2021.

Surety bond for Lila Canyon mine is through XL Specialty Insurance Company.

Insurance is covered by Lloyds Underwriters of London Policy PC30400W was issued on June 1, 2018 and expires on June 1, 2019. Minimum coverage requirements have been met. Explosion coverage is part of the policy. The certificate holder is listed as the State of Utah. The cancellation clause is acceptable to the Division.

UPDES Permit General UTG-040000, site specific UTG-040024. Permit effective September 1, 2013 and expires at midnight on August 31, 2018. There are two outfalls or discharge points associated with this permit. 001 Is for Sediment Pond #1 (Larger Pond) and 002 Mine Water.

UPDES Sanitary Permit #UT0026018/Biosolids #UTL0000000 effective December 1, 2015 and expires at midnight on November 30, 2020.

Air Quality Permit DAQE-AN0121850002-08 issued October 23, 2000 and still remains in effect.

Reclamation agreement is signed by the company and the Division on December 14, 1998.

SPCC Plan is dated August 2012. The plan is P.E. dated, Stamped and Signed by a Utah P.E. on August 14, 2014.

2. Signs and Markers

The mine identification sign was checked during the inspection. The sign identifies the name, address, phone number and mining permit number of the operator. The sign is in compliance.

3. Topsoil

The perimeter of the topsoil pile was checked. Protection is provided by an earthen berm. The berm is in place and functional.

4.a Hydrologic Balance: Diversions

Diversions through out the site were open and functional.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The second quarter 2018 inspections were done on 06/14/2018 for the small pond #2 and the large pond #1. The reports showed that the existing sediment levels are below the 60% elevation designated for cleaning.

4.e Hydrologic Balance: Effluent Limitations

The discharge submission reports for May and June 2018 were checked as part of the complete inspection. The information was submitted electronically to DEQ.

7. Coal Mine Waste, Refuse Piles, Impoundments

No refuse piles are associated with this mine site.

20. Air Quality Permit

Air Quality Permit DAQE-AN0121850002-08 issued October 23, 2000 and still remains in effect.

21. Bonding and Insurance

The bond is in place for this mining permit. The total current bond is \$1,799,000.00

22. Other

A longwall can is laying on the out slope of the new storage pad. This can needs to be brought back up to the interior of the storage pad.

Materials and equipment temporarily stored along the lower region of the main access road need to be transitioned into the storage yards need that room is available for this storage.

**NO
HUNTING**

UtahAmerican Energy, Inc.
HORSE CANYON MINE PART 'B'
Lila Canyon Mine
PO BOX 910
EAST CARBON, UT 84530
(435) 888-4000
DOGM #C 007/013
MSHA ID# 42-0224

Mine Identification Sign




#1 Sedimentation Pond



Mine Discharge



New Storage Pad



New Storage Pad



New Storage Pad