

0017

Document Information Form

Mine Number: C/007/016

File Name: Incoming

To: DOGM

From:

Person Joe C. Funk

Company United States Department of the Interior

Date Sent: August 10, 1987

Explanation:

Reclamation and Enforcement
TEN-DAY NOTICE

cc:

File in: C/007, 016, Incoming

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement
TEN-DAY NOTICE

Originating Office: OSM
625 Silver SW
Albuquerque, NM 87102
Telephone Number: (505) 766-1486

Number: X-87-02-006-006 TV 1

Ten-Day Notice to the State of Utah

You are notified that, as a result of a federal inspection (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: Beaver Creek Coal Co. County: Carbon Surface
(Or Operator if No Permit)
Mailing Address: PO Box 1378 Price, UT 84501 Underground
Permit Number: INA/007/017 Mine Name: Garden Ck 396 Other

NATURE OF VIOLATION AND LOCATION: Failure to post and maintain clear perimeter markers - entire disturbed area boundary

Section of State Law, Regulation or Permit Condition believed to have been violated: 817.11 (b), (d)

NATURE OF VIOLATION AND LOCATION: _____

Section of State Law, Regulation or Permit Condition believed to have been violated: _____

NATURE OF VIOLATION AND LOCATION: _____

RECEIVED
AUG 10 1987

DIVISION OF OIL
GAS & MINING
Section of State Law, Regulation or Permit Condition believed to have been violated: _____

Remarks or Recommendation: _____

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No 0017 Date 8-10-87
In C/ 007, 016, Incoming
For additional information

Date of Notice: 08/05/87

Signature of Authorized Rep.: Joe C Funk

Print Name and ID: Joe C Funk 006

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement
TEN-DAY NOTICE

Originating Office: OSM
625 Silver SW
Albuquerque, NM 87102

Number: X-87-02-006-006 TV 1

Telephone Number: (505) 766-1486

Ten-Day Notice to the State of Utah

You are notified that, as a result of a federal inspection (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: Beaver Creek Coal Co.
(Or Operator if No Permit)

County: Carbon

Surface

Mailing Address: PO Box 1378 Price, UT 84501

Underground

Permit Number: INA/007/017 Mine Name: Garden Ct 396

Other

NATURE OF VIOLATION AND LOCATION: Failure to post and maintain clear perimeter markers - entire disturbed area boundary

Section of State Law, Regulation or Permit Condition believed to have been violated: 817.11 (b), (d)

NATURE OF VIOLATION AND LOCATION: _____

Section of State Law, Regulation or Permit Condition believed to have been violated: _____

NATURE OF VIOLATION AND LOCATION: _____

RECEIVED

AUG 10 1987

DIVISION OF OIL

Section of State Law, Regulation or Permit Condition believed to have been violated: _____

Remarks or Recommendations: _____

Date of Notice: 08/05/87

Signature of Authorized Rep.: Joe C Funk

Print Name and ID: Joe C Funk 006

UNITED STATES
DEPARTMENT OF THE INTERIOR
OFFICE OF SURFACE MINING
219 CENTRAL AVE., NW
ALBUQUERQUE, NEW MEXICO 87102

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE, \$300



ATTN: Mr. Lowell Braxton

Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

CERTIFIED

P 201 228 995

MAIL



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

ACT/007/016 #2
Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

August 11, 1987

TO: Coal File
FROM; Richard V. Smith, Geologist *RVS*
RE: Field Confirmation of Subsidence Monitoring Stations-
Beaver Creek, Beaver Creek Coal Company, Gordon Creek
#2 and #7 Mine, ACT/007/016, Folder #2, Carbon County,
Utah

On June 19, 1987, Kathryn M. Mutz and Richard V. Smith conducted a partial inspection of the Gordon Creek #2 and 7 Mine (see Inspection Report dated 6/26/87). During the inspection, subsidence monitoring stations along Beaver Creek were not located.

Because of potential damage from livestock grazing, the subsidence monuments had been installed at ground level (telephone communication with Dan Guy, 8/11/87). Subsequent to the 6/19/87 inspection, the operator has cemented pieces of rebar into the original monuments, flagged the rebar and installed aluminum caps with identification numbers at all subsidence monitoring stations. These remedial actions should allow easy confirmation of subsidence monitoring stations during future inspections.

djh
cc: D. Guy, Beaver Creek
J. Whitehead
K. Mutz
9206R/20