0017

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/016

Inspection Date 6/28/88

Permittee/Operator Name Beaver Creek Coal Co

Business Address Box 1378

City Price State UT Zip 84501

Mine Gordon Creek 2 & 7 ☐ Surface ☒ Underground ☐ Other

County Carbon State

Company Official(s) Dan Guy

State Official(s) Jim Fricke, Rick Smith

Time of inspection 1:30 ☐ a.m. ☒ p.m. to 4:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 5/17/88 Weather conditions Cloudy, light rain

Acreage 2289 ☒ Permitted 9.0 ☒ Disturbed ☐ Regraded ☐ Seeded 9.0 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date 6/28/88

Please number comments to correspond with topics on previous page.

3. The operator has installed a silt fence between the highwall and topsoil storage pile. The silt fence will provide the recommended (5/17/88, inspection) protection

4b. Items 4 & 5 of the 5/17/88 inspection write-up ~~for~~ were not completed as of the 6/28/88 inspection. The operator did provide ~~a~~ in-house documentation of the required maintenance. The completion date for the maintenance was 6/30/88. Both diversions are in a functional condition. The operator stated that the maintenance would be completed by 6/30/88.

4c. Pond inspection report forms for ponds 2, 7A, Sweet's and the Snow Pond were reviewed. All ponds are functioning properly and were inspected during May of 1988.

4d. The operator must maintain the straw bales along the Class I access road. The bales are functional but require re-installation. The operator was given until 8/27/88 to key-in and construct the straw bale structures such that a spillway exists.

Copy of report mailed to Dan Guy (BCCC), Brian Smith (OSM)

Copy of report given to Joe Helfrich (DOGM),

Inspector's signature Jim Trickle No. 22

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE