11-28-89

UTAH NATURAL RESOURCES
Oil, Gas & Mining

0021

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RVS

inspection report

Permit No. 007/016

Inspection Date NOV. 2, 1989

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address P.O. BOX 1378

City PRICE State UTAH Zip 84501

Mine GORDON CR 2, 7+8 ☐ Surface ☒ Underground ☐ Other

County CARBON State

Company Official(s) NONE

State Official(s) TOM MUNSON

Time of inspection 1:00 ☐ a.m. ☑ p.m. to 1:30 ☐ a.m. ☑ p.m. ☒ Partial ☐ Complete

Date of last inspection SEPT. 30 1989 Weather conditions SUNNY

Acreage 2287 ☒ Permitted 9 ☒ Disturbed ☐ Regraded ☐ Seeded 9 ☒ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a – Stream channel diversions	☐	☐	☐	☐
b – Diversions	☐	☐	☐	☐
c – Sediment ponds and impoundments	☑	☐	☐	☑
d – Other sediment control measures	☐	☐	☐	☐
e – Surface and groundwater monitoring	☐	☐	☐	☐
f – Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☑	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. 007/016

Inspection Date 11/2/89

Please number comments to correspond with topics on previous page.

4C. The sediment pond is in the process of being cleaned. Verbal approval was given for this maintenance item on 11/1 by Tom Munson to Dan Guy. A water tight truck is being used to transport the waste material to the approach waste disposal site at C.V. Spur.

16 b. All drainage controls appeared clean and functioning as intended

Copy of report mailed to Brian Smith (OSM), Dan Guy (BCCC

Copy of report given to Joe Helfrich, PFO

Inspector's signature Thomas Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer