7175

0007

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Gok pgl

inspection report

Permit No. ACT/007/016

Inspection Date 4/3/90

Permittee/Operator Name Beaver Creek Coal Company

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine Body Creek #2, #7, & #8 ☐ Surface ☑ Underground ☐ Other

County Carbon State Utah

Company Official(s) DAN GUY

State Official(s) Susan White & Pam Grubaugh-Littig

Time of inspection 11:00 ☑ a.m. ☐ p.m. to 12:00 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete

Date of last Inspection 3/13/90 Weather conditions COOL and SUNNY

Acreage 2289 ☑ Permitted 18 ☑ Disturbed ☐ Regraded ☐ Seeded 18 ☑ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	✓			✓
2. Signs and markers				
3. Topsoil	✓			✓
4. Hydrologic balance				
a – Stream channel diversions				
b – Diversions				
c – Sediment ponds and impoundments	✓			✓
d – Other sediment control measures				
e – Surface and groundwater monitoring				
f – Effluent limitations				
5. Explosives				
6. Development waste and spoil disposal				
7. Coal processing waste				
8. Noncoal waste				
9. Protection of fish, wildlife, and related environmental values				
10. Slides and other damage				
11. Contemporaneous reclamation				
12. Backfilling and grading				
13. Revegetation				
14. Subsidence control				
15. Cessation of operations				
16. Roads				
a – Construction				
b – Drainage controls	✓			✓
c – Surfacing				
d – Maintenance	✓			✓
17. Other transportation facilities				
18. Support facilities and utility installations				

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-1

an equal opportunity employer

11/86 001049

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date 4/3/90

Please number comments to correspond with topics on previous page.

1. Reviewed permit, bond and insurance at Beaver Creek Coal Company offices. Documents are current and in order.
4c. Sedimentation ponds have a small amount of water.
16b. The drainages are operable. The operator stated that ~~the~~ spring maintenance will be undertaken next week to put all drainages in excellent working order.
3. The #7 topsoil pile had silt fences above the pile to catch falling rocks and other debris. The fence is working well as required for its function, i.e. holding rocks.
16d. The haulage road was being watered to keep dust controlled.

Copy of report mailed to Brian Smith (OSM, AFO)

Copy of report given to ~~Dan~~ Guy (BCC) and Joe Helfrich (DOGM)

Inspector's signature Pamela Grubaugh-Littig No. 20 4/3/90

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049