UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ~~ACT/007/010~~
Inspection Date 12/13/90

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State UT Zip 84501
Mine Gordon Creek 2,7,8 ☐ Surface ☑ Underground ☐ Other
County Carbon State UT
Company Official(s) Dan Guy
State Official(s) Susan White
Time of inspection 10:00 ☑ a.m. ☐ p.m. to 11:00 ☑ a.m. ☐ p.m. ☑ Partial ☐ Complete
Date of last inspection 11/29/90 Weather conditions Cold and Snowing
Acreage 2289 ☐ Permitted 18 ☐ Disturbed ☐ Regraded ☐ Seeded 18 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☑
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☑	☐	☐	☑
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date 12/13/90

Please number comments to correspond with topics on previous page.

~~[illegible]~~ At the time of inspection it was snowing with 4 to 6 inches of new snow on the ground. The site was quiet with only portal sealing activities going on.

2. All signs and markers were in place. ~~The operator~~ It was suggested to the operator that all disturbed area markers be evaluated as to reclamation and demolition activities. If more space is needed for these activities now is the time to request changing markers.

15. #2 mine portal was sealed in approximately 1986
#8 mine portal (and fan and conveyor portals) was sealed in December 1990.
#7 mine portal (and associated portals) was being sealed at the time of inspection.
#8 mine and fan portal seals were observed on this inspection.
The Bathhouse and water tanks will be removed from site prior to winter closure.

Copy of report mailed to Dan Guy (BCC); John Kathman (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Susan M. White No. 55

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049