

pgl *[Signature]*

inspection report

Permit No. ACT/007/016

Inspection Date March 7, 1991

Permittee/Operator Name Beaver Creek Coal Company

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine Gordon Creek 2, 7, & 8 Surface Underground Other

County Carbon State Utah

Company Official(s) Dan Guy

State Official(s) Jess Kelley

Time of inspection 8:30 a.m. p.m. to 2:00 a.m. p.m. Partial Complete

Date of last inspection February 27, 1991 Weather conditions Sunny and cold

Acreage 2289 Permitted 18 Disturbed Regraded Seeded 18 Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	10. Slides and other damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11. Contemporaneous reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Stream channel diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14. Subsidence control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Sediment ponds and impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	15. Cessation of operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
- Other sediment control measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16. Roads				
- Surface and groundwater monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Construction	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Effluent limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Drainage controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Maintenance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal processing waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	17. Other transportation facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date March 7, 1991

Please number comments to correspond with topics on previous page.

Operations at this site ceased in November of 1990. Cleanup, structure and material removal, and portal sealing continued through December of 1990. The day of the inspection, the site was inaccessible to wheeled vehicles. The entire site was covered by 2 feet of fresh snow which made observation of all but the largest surface features completely impossible. Nevertheless, this inspector examined the site and discussed the upcoming reclamation work at length with Beaver Creek Coal Company representative Dan Guy.

2. SIGNS AND MARKERS--Mine Identification signs and perimeter markers are in place and in good repair.

15. CESSATION OF OPERATIONS--As mentioned before, the site is completely inactive and snowbound. All portals have been sealed, including the portals to the #8 mine, which was the last part of the operation to be shut down. The main entrance gate to the property was locked and prevented entrance to the property by unauthorized individuals.

16. SUPPORT FACILITIES AND UTILITY INSTALLATIONS--The bathhouse trailer and the office trailer have been moved from the site to the Trail Mountain #9 site. Other than these buildings, removal of major structures has yet to begin.

Copy of report mailed to Dan Guy/Beaver Creek; John Kathman/OSM

Copy of report given to Joe Helfrich/DOGM

Inspector's signature *Jesse W. Kelley* No. 34

WHITE--DOGM YELLOW--OSM PINK--PERMITTEE/OPERATOR GOLDENROD--NOV FILE