

INSPECTION REPORT

Partial Complete XXX Exploration
 Inspection Date: 03/06/2003 Time: 09:30-4:30
 Date of Last Inspection: 02/12/003

Mine Name: Gordon Creek 2, 7, & 8 Mine County: Carbon Permit Number: C/007/016
 Permittee and/or Operator's Name: Mountain Coal Company
 Business Address: HC Box 380, Helper, Utah 84526
 Company Official(s): Dan Guy Federal Official(s): None
 State Official(s): Joe Helfrich
 Weather Conditions: Sunny, 35
 Type of Mining Activity: Underground XXX Surface Prep Plant Other
 Existing Acreage: Permitted 180 Disturbed 34.88 Regraded 34.88 Seeded 34.88
 Status: Active Reclamation XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:	<input checked="" type="checkbox"/>			
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:	<input type="checkbox"/>			
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/007/016

DATE OF INSPECTION: 03/06/2003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permit for this reclaimed site was renewed effective August 28, 1999. There is one amendment pending, #AM02A, (Rock Gabion removal) submitted on March 13, 2002. The TA contained one deficiency that the applicant was required to demonstrate that no additional contributions of suspended solids were occurring in the receiving stream channel and prevent material damage outside the permit area. No samples have been taken to date. However, current weather patterns may provide an opportunity to obtain a sample.

2. SIGNS AND MARKERS

The signs located at the access at the end of the county road were in good repair and contained the required information.

3. TOPSOIL

As of the time of this inspection, no additional topsoil from the logging road above the reclaimed area had been transported to the flatter low gradient areas of the first side channel (SD #6) and the sediment pond. The road is a county road and the county agreed to divert the runoff from the road away from the watershed that drains to the sediment pond.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions appeared to be in good repair at the time of this inspection as there was approximately 6" of snow covering the site.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The fourth quarter 2002 pond inspections for the 2, 7, & 8 Sediment Pond, Jacobs Pond, and Sweets pond indicated that the ponds were stable and showed no signs of structural weakness. The ponds were inspected on 11/12/2002.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The DMR's were current through January 2003 reporting no discharge for those time periods. Hard copies of the fourth quarter monitoring data were available for review. Fourth quarter 2002 water monitoring data has been submitted electronically. The UPDES permit is valid through April 30, 2003.

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/007/016

DATE OF INSPECTION: 03/06/2003

21. BONDING AND INSURANCE

Liberty Mutual Insurance Company holds the \$641,443.00 bond. St. Paul Fire & Marine Insurance Company carries a \$500,000 general liability coverage that expires 07/31/2003.

Inspector's Signature: _____ Date: March 10, 2003
Joseph C. Helfrich #1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Chris Hansen, Canyon Fuel Company
Dan Guy, Blackhawk Engineering
Price Field office
O:\007016.GC2\Compliance\2003\C_0306.doc