0012

RVS

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/007/017

Inspection Date SEPT 30, 1989

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address P.O. BOX 1378

City PRICE State UT Zip 84501

Mine GORDON CREEK 3 & 6 ☐ Surface ☒ Underground ☐ Other

County CARBON State UT

Company Official(s) NONE

State Official(s) BILL WAKMACK

Time of inspection 12:00 ☐ a.m. ☒ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection AUG 9, 1989 Weather conditions CLEAR & WARM

Acreage 160 ☒ Permitted 34.4 ☒ Disturbed 28 ☒ Regraded 28 ☒ Seeded 28 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☐	☐	☐	☐
c. Sediment ponds and impoundments	☐	☐	☐	☐
d. Other sediment control measures	☒	☐	☐	☒
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☐	☐
b. Drainage controls	☒	☐	☐	☐
c. Surfacing	☐	☐	☐	☐
d. Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/007/017

Inspection Date SEPT 30, 1989

Please number comments to correspond with topics on previous page.

2. SIGNS & MARKERS: THE APPROPRIATE MINE ID SIGN & PERIMETER MARKERS WERE IN PLACE & IN GOOD REPAIR. THE ASSOCIATED FENCE WAS ALSO FUNCTIONAL, NO BREAKS OR OPENINGS WERE OBSERVED.

4d. OTHER SED CONTROLS: SILT FENCES WERE OPERATIONAL & SHOWED NO SIGN OF DETERIORATION OR COLLAPSE. DRAINAGE AREAS WERE DRY; EVIDENCE OF RECENT RUNOFF WAS NOT OBSERVED.

Copy of report mailed to SEC: JOE HELFRICH (DOGM), BRIAN SMITH (OSM), PAN GUY (BCCC)

Copy of report given to PFO

Inspector's signature William A. Warmack 10/2/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049