0004

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gdh pgl

7080

inspection report

Permit No. ACT/007/017
Inspection Date 4/3/90

Permittee/Operator Name Beaver Creek Coal Company
Business Address P.O. BOX 1378
City PRICE State Utah Zip 84501
Mine Gordon Creek #3 & #6 ☐ Surface ☑ Underground ☐ Other
County Carbon State
Company Official(s) DAN GUY
State Official(s) SUSAN WHITE & PAM GRUBAUGH-LITTIG
Time of inspection 8:00 ☑ a.m. ☐ p.m. to 10:45 ☑ a.m. ☐ p.m. ☑ Partial ☐ Complete
Date of last inspection 3/13-16/90 Weather conditions COOL & Sunny
Acreage 668 ☑ Permitted 34 ☑ Disturbed 28 ☑ Regraded 28 ☑ Seeded 28 ☑ Bonded
Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☑
2. Signs and markers	☑	☐	☐	☑
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☑	☐	☐	☑
d Other sediment control measures	☑	☐	☐	☑
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☑	☐	☐	☑
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☑	☐	☐	☑
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-1

an equal opportunity employer

11/86 001049

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/017

Inspection Date 4/3/90

Please number comments to correspond with topics on previous page.

1. Reviewed permits at Beaver Creek Coal Company office). The reclamation permit, bond, and insurance are all in order.
2. Signs are posted and clearly legible as required at the reclaimed site.
4c There is water standing in the upper sedimentation pond. There are signs that water has been flowing in the reclaimed stream channel.
4d. Silt fences were observed and in good operating condition
13. There are signs that elk have been in the revegetated areas. Willows are growing along the reclaimed stream channel and look vigorous.

NOTE: No erosion was evident ~~along the~~ at the reclaimed site.

Copy of report mailed to Brian Smith (OSM, AFO)

Copy of report given to Don Guy (BCCC), Joe Helfrich (DOGM

Inspector's signature [signature] 4/3/90 No. 20

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE