



Handwritten signatures

inspection report

Permit No. ACT/007/017

Inspection Date March 28, 1991

Permittee/Operator Name Beaver Creek Coal Company

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine Gordon Creek 3 & 6 Surface Underground Other

County Carbon State Utah

Company Official(s) Dan Guy

State Official(s) Jess Kelley

Time of inspection 2:00 a.m. p.m. to 4:30 a.m. p.m. Partial Complete

Date of last inspection February 27, 1991 Weather conditions Cold and sunny

Acreage 668 Permitted Disturbed Regraded Seeded Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

Table with 4 columns: YES, NO, N/A, COMMENTS. Rows include: 1. Permits, 2. Signs and markers, 3. Topsoil, 4. Hydrologic balance, 5. Explosives, 6. Development waste and spoil disposal, 7. Coal processing waste, 8. Noncoal waste, 9. Protection of fish, wildlife, and related environmental values, 10. Slides and other damage, 11. Contemporaneous reclamation, 12. Backfilling and grading, 13. Revegetation, 14. Subsidence control, 15. Cessation of operations, 16. Roads, 17. Other transportation facilities, 18. Support facilities and utility installations.

INSPECTION REPORT COMMENTS

Permit No. ACT/007/017

Inspection Date March 28, 1991

Please number comments to correspond with topics on previous page.

The day of the inspection was cold, windy and sunny. The entire canyon was covered with a blanket of deep, drifted snow. This made the site accessible only on foot and made all but the most superficial features invisible.

2. SIGNS & MARKERS

The mine identification sign at the entrance to the property is in good repair. The disturbed area markers are likewise in place and in good repair.

18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS

The main gate at the entrance to the property is kept locked and is performing very well its function of keeping unauthorized persons off the property.

Fences are all in good repair. They appear to be very effective in keeping wildlife and even livestock off the property as no tracks of any kind were observed within the area surrounded by the fences.

Copy of report mailed to Dan Guy/Beaver Creek Coal Company; John Kathman/OSM

Copy of report given to Ine Helfrich/DOGM

Inspector's signature Jesse W. Kelley No. 34

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE