



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten initials

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: ___ Exploration: ___
Inspection Date & Time: 4/27/94 3:00 to 3:30
Date of Last Inspection: 3/24/94

Mine Name: Gordon Creek #3 & #6 County: Carbon Permit Number: ACT/007/017
Permittee and/or Operator's Name: Mountain Coal Company
Business Address: P.O. Box 591, Somerset, CO 81434
Type of Mining Activity: Underground X Surface ___ Prep. Plant ___ Other ___
State Official(s): Susan White
Company Official(s): Dan Guy and Dana Ballard
Federal Official(s): None
Weather Conditions: Cool with scattered snow and rain
Existing Acreage: Permitted-668 Disturbed-28 Regraded-0 Seeded-28 Bonded-28
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: ___ Exploration/ ___ Active/ ___ Inactive/ ___ Temporary Cessation/ ___ Bond Forfeiture
Reclamation (___ Phase I/ ___ Phase II/ ___ Final Bond Release/ ___ Liability ___ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Contains 21 rows of inspection items with checkboxes.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/017

DATE OF INSPECTION: 4/27/94

(Comments are Numbered to Correspond with Topics Listed Above)

13. REVEGETATION

The site was green and the vegetation appeared vigorous. Beaver had cut young Aspen trees adjacent to the road for use in dams.

21. BONDING & INSURANCE

The operator has applied for Phase II bond release on this site. The on site inspection is scheduled for May 18, 1994. The Division's vegetation survey in summer of 1993 indicate that the site has as much vegetative cover as the reference area.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Kathleen Welt (MCC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White # 35 Date: 5/10/94