

0010



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

AGHD071017

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 5/25/95 9:00 TO 11:00
Date of Last Inspection: 4/25/95

Mine Name: Gordon Creek #3 & #6 County: Carbon Permit Number: ACT/007/017
Permittee and/or Operator's Name: Mountain Coal Company
Business Address: P.O. Box 591, Somerset, CO 81434
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Official(s): Susan White
Company Official(s): Dan Guy
Federal Official(s):
Weather Conditions: cool and showers
Existing Acreage: Permitted-668 Disturbed-28 Regraded-0 Seeded-28 Bonded-28
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (X Phase I/ X Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.



INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/017

DATE OF INSPECTION: 5/25/95

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

a. Diversions - The diversion along side the road, adjacent to the middle pad area was regraded as discussed in the previous inspection. One spot still does not drain, this must be corrected. A long term solution should be provided for this spot, prior to bond release since the land owner will probably not preform maintenance.

b. Sediment Ponds - The upper cell of the sediment pond contained water, the lower cell was dry.

13. REVEGETATION

The vegetation looked very good, with strong vigorous growth. The spring has been unusually wet in this area. Vegetation sampling for the first year of two, for Phase III bond release should occur late June or early July.

Copy of this Report:

Mailed to: Tom Ehmett (OSM), Paige Beville (MCC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: *Susan M. White* # 35 Date: 6/1/95