



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

PE  
1-28-87

*File*

*gcl*

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 14, 1987  
11:30 a.m. to 1:30 p.m.

Permittee and/or Operators Name: Soldier Creek Coal Company  
Business Address: P. O. Box I Price, Utah 84501  
Mine Name: Soldier Canyon Permit Number: ACT/007/018  
Type of Mining Activity: Underground  Surface  Other   
County: Carbon  
Company Official (s): Dave Spillman  
State Official(s): Holland Shepherd  
Partial:  X Complete:  Date of Last Inspection: June 4, 1987  
Weather Conditions: Sunny, hot, no runoff  
Acreage: Permitted 2973 Disturbed 7 Regraded 0 Seeded 0 Bonded 7  
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( X )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/018

DATE OF INSPECTION July 14, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

4d. SEDIMENT CONTROLS:

All sediment controls appeared to be functioning adequately at this site.

4f. EFFLUENT LIMITATIONS:

No discharges from any of the operator's three discharge locations were evident during this inspection.

Copy of this Report:

Mailed to: Dave Spillman, SCCC; Donna Griffin, OSM

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number: Holland Shepherd #9

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/018

DATE OF INSPECTION July 14, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

4d. SEDIMENT CONTROLS:

All sediment controls appeared to be functioning adequately at this site.

4f. EFFLUENT LIMITATIONS:

No discharges from any of the operator's three discharge locations were evident during this inspection.

Copy of this Report:

Mailed to: Dave Spillman, SCCC; Donna Griffin, OSM

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number: Holland Shepherd #9 Date: July 20, 1987