

2-8-89
7120

0004



UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N 89-28-1-1

notice of violation

To the following Permittee or Operator:

Name Soldier Creek Coal Co.

Mine Soldier Canyon Surface Underground Other

County Carbon State Utah Telephone _____

Mailing Address P.O. Box I Price Utah 84501

State Permit No. ACT/007/018

Ownership Category State Federal Fee Mixed

Date of inspection Feb 1, 1989, 19____

Time of inspection 9 00 a.m. p.m. to 3 30 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing Feb 1, 1989 Time of service/ mailing 3:15 a.m. p.m.

Chris Allen
Permittee/Operator representative
[Signature]
Signature

Mine Personnel
Title

Daron R. Haddock
Division of Oil, Gas & Mining representative
[Signature]
Signature

Reclamation Specialist
Title
#28
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 88-28-1-1

Violation No. 1 of 1

Nature of violation

Failure to pass surface drainage from the disturbed area through a sedimentation pond or treatment facility before leaving the permit area and to prevent to the extent possible additional contributions of sediment to stream flow outside the permit area.

Provisions of act, regulations or permit violated

UMC 817.42 (a) (1)
UMC 817.45 i

Portion of operation to which notice applies

Snow pile pushed off the disturbed area in the south corner of the Mine parking lot.

Remedial action required (including any interim steps)

Recover to the extent possible snow + debris that is on the south side of the guard rail + berm. Install straw bales or silt fence around the outside perimeter of the snow pile.

Abatement time (including interim steps)

February 8th 1989 by 3 P.M.