

0004



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

Michael O. Leavitt  
Governor  
Ted Stewart  
Executive Director  
James W. Carter  
Division Director

1594 West North Temple, Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
(801) 538-5340  
(801) 359-3940 (Fax)

Partial: XXX Complete:      Exploration:     

Inspection Date & Time: 9/30/97 / 8:45a.m. - 11:00a.m.

Date of Last Inspection: 8/28/97

Mine Name: Soldier Canyon Mine County: Carbon Permit Number: ACT/007/018

Permittee and/or Operator's Name: Canyon Fuel Company

Business Address: P.O. Box 1029, Wellington, Utah 84542

Type of Mining Activity: Underground XXX Surface      Prep. Plant      Other     

Company Official(s): Steve Nye

State Officials(s): Peter Hess Federal Official(s): None

Weather Conditions: Cool, 70's, Clear

Existing Acreage: Permitted- 5186.17 Disturbed- 24 Regraded- 0 Seeded- 0 Bonded- 95.2

Increased/Decreased: Permitted-      Disturbed-      Regraded-      Seeded-      Bonded-     

Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture

Reclamation (     Phase I/      Phase II/      Final Bond Release/      Liability      Year)

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June)_____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>



*John*

**INSPECTION REPORT**  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/018

DATE OF INSPECTION: 9/30/97

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL

Mr. Paul Baker, Reclamation Biologist with the SLC-DOGM has made an evaluation of the topsoil piles for the Mine. He indicated to me that the brown vegetation on the piles is expired cheat grass. Mr. Spillman indicated this day that Mr. Baker intends to conduct research to assist in the control of the cheat grass for next year. Enough perennials remain on the piles to effectively control wind and water erosion.

4a. HYDROLOGIC BALANCE: DIVERSIONS


The 12 inch CMP designated as culvert 7 on drawing number E 064 (Exhibit 7.32-1), (culvert is located on west corner of Mine sub-station) had it's inlent end plugged with gravel by approximately two-thirds. Mr. Nye cleaned this during the inspection.

The permittee is in the process of repairing the underground 30 inch bypass culvert which runs in front of the maintenance shop. According to Mr. Spillman, this diversion became blocked, and upon further investigation, it was determined that the culvert had rotted away through the years.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Dave Spillman (Canyon Fuel) Henry Austin (OSM)  
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office  
Date: October 2, 1997

Inspector's Signature:  #39  
Peter Hess