



Jah

NO. N 89-28-9-1

To the following Permittee or Operator:

Name Andalex Resources, Incorporated

Mine Centennial Project Surface Underground Other

County Carbon State Utah Telephone 637-5385

Mailing Address PO Box 902 Price Utah

State Permit No. ACT/007/019

Ownership Category State Federal Fee Mixed

Date of inspection 10/18/89, 19__

Time of inspection 8:30 a.m. p.m. to 2:15 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling 10/18/89 Time of service/mailling 2:15 a.m. p.m.

Mike Glasson
Permittee/Operator representative

Senior Geologist
Title

Michael W. Glenn
Signature

Daron R. Haddock
Division of Oil, Gas & Mining representative

Reclamation Specialist
Title

Daron R. Haddock
Signature

#28
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

2819

NOTICE OF VIOLATION NO. N 89-28-9-1

Violation No. 1 of 1

Nature of violation

Failure to conduct mining activities in accordance with the terms & conditions of the approved permit and mining plan. i.e. The NPDES permit reporting requirements.

Provisions of act, regulations or permit violated

UMC 771.19

UMC 817.52 (b)

Portion of operation to which notice applies

NPDES Reporting requirements.
2nd quarter DMR were submitted late (9/29/89)
" " " showed no discharge when analytical report confirmed that a discharge had occurred (6/20/89)
3rd quarter DMR showed Suspended Solids as 39mg/l which exceeded limitations. No notification of exceedance was given.

Remedial action required (including any interim steps)

An after the fact violation.
remedial action would be to start reporting in accordance with the approved permit,

Abatement time (including interim steps)

None possible
Terminated same day.