



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

get
RECEIVED
DEC 10 1990
NRZ

PERMIT NO.: ACT/007/019
Inspection Date: November 27, 1990
DIVISION OF OIL, GAS & MINING

Permittee and/or Operators Name: Andalex Resources, Inc.
Business Address: P.O. Box 902
City: Price State: Utah Zip: 84501
Mine Name: Centennial Project
County: Carbon State: Utah
Type of Mining Activity: Underground Surface Other
Company Official (s): Laine Adair
State Officials (s): Stephen J. Demczak
Time of Inspection: 2:15 () a.m. (X) p.m. to 4:20 () a.m. (X) p.m.
Partial Complete: Date of Last Inspection: _____
Weather Conditions: Clear/Sunny
Acreage: Permitted 3368 Disturbed 34 Regraded Seeded Bonded 34
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	(X)	()	()	(X)
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/019 INSPECTION DATE November 27, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

b. Diversions:

The culverts inlets and outlets were all clear of debris and functioning properly at the time of inspection.

c. Sediment Ponds & Impoundments:

Sediment ponds were functioning properly and no rills were observed.

d. Other Sediment Controls:

A few new hay bails were installed prior to inspection. There were a few beginning to accumulate sediment. Management will take action cleaning hay bails before problems develop.

5. EXPLOSIVES:

All explosive storage units were locked and grounded. No problems noted.

Copy of report:

Mailed to: Mike Glasson (Andalex)

Mailed to SLC for: Brian Smith (OSM) Daron Haddock (DOGM)

Filed to: PFO

Inspectors Signature and Number: Stephen Demczak #39 Date: 12/6/90

Stephen Demczak