

0009



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Handwritten initials/signature

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

PERMIT NO.: ACT/007/019 Inspection Date: August 20, 1991
 Permittee and/or Operators Name: Andalex Resources Inc.
 Business Address: P.O. Box 902
 City: Price State: Utah Zip: 84501
 Mine Name: Centennial Project
 County: Carbon State: Utah
 Type of Mining Activity: Underground XX Surface Other
 Company Official (s): Mike Glasson
 State Officials (s): Stephen J. Demczak
 Time of Inspection: 9:00 (XX) a.m. () p.m. to 12:30 () a.m. (XX) p.m.
 Partial XX Complete: Date of Last Inspection: July 26, 1991
 Weather Conditions: Warm 90's
 Acreage: Permitted 3368 Disturbed 34 Regraded 0 Seeded 0
 Bonded 34 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/019 INSPECTION DATE August 20, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits - The drainage map was reviewed and compared to field placement. There was need for additional detail in certain areas. The operator will upgrade the map and send it to DOGM.

- 4c. Diversions - The diversions were inspected and compared with drainage map with no major problems noted. The diversions were performing to design standards.

- 4d. Sediment Ponds and Impoundments - The uppermost sediment is scheduled for clean out this summer on cell #1. At the time of inspection no ponds were discharging, but some did contain some water runoff. There were no signs of erosion to slope or inlet of pond.

**An AVS check was made with no new changes occurring.

Copy of report:

Mailed to: Andalex Resources, Inc.
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)
Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39
Date: 8/27/91

Stephen J. Demczak