



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: XX Complete: Exploration:
Inspection Date & Time: 11-22-95 / 7:30a.m.-11:00a.m.
Date of Last Inspection: 10/11/95

Mine Name: Centennial Project County: Carbon Permit Number: ACT/007/019
Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P. O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Mike Glasson
State Officials(s): Stephen J. Demczak Federal Official(s):
Weather Conditions: Cool 40's
Existing Acreage: Permitted- 5063 Disturbed- 34 Regraded- 0 Seeded- 0 Bonded- 34
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; 2. SIGNS AND MARKERS; 3. TOPSOIL; 4. HYDROLOGIC BALANCE; 5. EXPLOSIVES; 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; 8. NONCOAL WASTE; 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; 10. SLIDES AND OTHER DAMAGE; 11. CONTEMPORANEOUS RECLAMATION; 12. BACKFILLING AND GRADING; 13. REVEGETATION; 14. SUBSIDENCE CONTROL; 15. CESSATION OF OPERATIONS; 16. ROADS; 17. OTHER TRANSPORTATION FACILITIES; 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS; 19. AVS CHECK (4th Quarter-April, May, June) (date); 20. AIR QUALITY PERMIT; 21. BONDING & INSURANCE.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: 11/22/95

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

The permittee has requested that the Division extend time to address deficiencies in the mid-term review.

2. SIGNS AND MARKERS -

The identification signs were reviewed and had the correct information displayed on the signs.

4A. DIVERSIONS -

The diversions were spot-checked and two culverts were in need of maintenance. Some sediment has started to build-up at the outlets. The operator has committed to cleaning out the culverts.

4B. SEDIMENT PONDS -

The permittee has cleaned out the sediment pond below the three cell catch basin. The material was moved to the Wildcat loadout refuse area.

The ponds were dry and no hazardous conditions were noticed during the inspection.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Mike Glasson (Andalex)

Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: November 23, 1995

Inspector's Signature: _____

Stephen J. Demczak

#39