



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

INSPECTION REPORT

Handwritten initials/signature: PGL

Partial: XXX Complete: Exploration:
Inspection Date & Time: 11/28/2001 / 8:20-10:30 AM
Date of Last Inspection: 10/31/2001

Mine Name: Centennial Project County: Carbon Permit Number: C/007/019
Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P.O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Mr. Mike Glasson, Senior Geologist
State Official(s): Peter Hess Federal Official(s): None
Weather Conditions: Clear/cold/ temperature <32 degrees Fahrenheit/ Ground is snow covered.
Existing Acreage: Permitted 5179.49 Disturbed 35.27 Regraded Seeded
Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, SIGNS AND MARKERS, TOPSOIL, HYDROLOGIC BALANCE, etc.

**INSPECTION REPORT**

(Continuation sheet)

PERMIT NUMBER: C/007/019

DATE OF INSPECTION: 11/28/2001

( COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE )

**Note:** As observed today, a fresh product pile was observed on the Aberdeen Mine coal storage pad. Coal is also being actively produced in the Pinnacle Mine.

**1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE**

Mr. Glasson informed the Division this day that the permittee is preparing an incidental boundary change to extend the Mine life of the Centennial project. This IBC will be relative to the Castle Gate LMU.

**4A. HYDROLOGIC BALANCE: DIVERSIONS**

The majority of the surface drainage diversions are under snow; the inlets and outlets of any culverts which were not buried were capable of functioning as designed.

**4D. HYDROLOGIC BALANCE: WATER MONITORING**

The permittee has submitted the third quarter water monitoring information to the Division. The majority of the sites were reported as dry; analysis for Well #1 was submitted.

**8. NONCOAL WASTE**

The permittee continues the removal of machinery from the equipment storage area adjacent to the Apex Mine truck loading facility. Some is being junked; other equipment is being sold off, or shipped to the West Ridge Mine, depending on need and condition.

Inspector's Signature: \_\_\_\_\_

  
Peter Hess #46

Date: November 30, 2001

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM  
Mike Glasson, Andalex  
Price Field office

O:\007019.CEN\Compliance\2001\p\_1128.wpd