

INSPECTION REPORT

Partial Complete Exploration
 Inspection Date: 03/21/2003/ Time: 9:30 – 12:30
 Date of Last Inspection: 02/25/2003

Mine Name: Centennial Project County: Carbon Permit Number: C/007/019
 Permittee and/or Operator's Name: Andalex Resource, Inc.
 Business Address: P.O. Box 902, Price, Utah 84501
 Company Official(s): Mike Glasson
 State Official(s): Karl R. Houskeeper Federal Official(s): None
 Weather Conditions: Clear, Temp 47°F
 Type of Mining Activity: Underground Surface Prep Plant Other
 Existing Acreage: Permitted 5419.49 Disturbed 35.27 Regraded Seeded
 Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2.	SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3.	TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.	SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c.	OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d.	WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e.	EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5.	EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8.	NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10.	SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11.	CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12.	BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13.	REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14.	SUBSIDENCE CONTROL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15.	CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.	DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17.	OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19.	AVS CHECK (4 th Quarter- April, May, June)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20.	AIR QUALITY PERMIT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21.	BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/007/019

DATE OF INSPECTION: 03/21/2003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The current DOGM permit was re-issued effective 05/24/2002, to include the Mathis Tract, and expires 01/06/2007.

- Certificate of Insurance issued 07/01/2002 and terminates 07/01/2003.
- Reclamation agreement is dated February 1990 and signed by both parties.
- UPDES permit UTG040008 effective 08/01/1998 and expires midnight 04/30/2003.
- Air Quality permit DAQE-997-96, issued October 25, 1996.
- SPCC Plan dated 12/25/2002.

The operator is aware of the expiration date associated with the UPDES permit. The operator indicated that the appropriate information and request have been submitted to Water Quality to renew this permit.

2. SIGNS AND MARKERS

The mine permit ID sign located at the contact point of public access to the permit area contained the required information. Other signs and markers observed during the inspection meet the coal rules.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

Reviewed the annual pond inspection and certification. The annual pond inspection serves as the fourth quarter 2002 pond inspection. Quarterly pond inspections for first quarter through third quarter 2002 were also reviewed in addition to the fourth quarter 2002 pond inspection.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Water monitoring is current. Fourth quarter 2002 water monitoring information has been submitted and uploaded into the EDI website. January and February 2003 UPDES information is also contained in the EDI website.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

A review of the discharge monitoring reports (DMR's) indicates that no effluent parameters were exceeded.

8. NONCOAL WASTE

Several areas through out the site contained pieces of noncoal waste that have blown from the storage pad areas. The operator made note of the different locations and will have the noncoal waste items picked up and placed in the appropriate noncoal waste storage area.

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/007/019

DATE OF INSPECTION: 03/21/2003

20. AIR QUALITY PERMIT

The air quality permit DAQE-997-96 referenced above remains in effect.

21. BONDING AND INSURANCE

The insurance referenced in item #1 above is through Federal Insurance Company, policy #37102594. The insurance has explosion coverage, meets the minimum coverage requirements, lists the Division as the certificate holder, and has the proper language on the notification policy.

Bond No. SU34593 is for \$381,839 and Bond No. SU1354086 is for \$699,000. Both bonds remain in effect for the term of the permit and are through Utica Mutual Insurance Company.

Inspector's Signature: _____ Date: March 21, 2003
Karl R. Houskeeper #49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Mike Glasson, Andalex
Price Field office
O:\007019.CEN\Compliance\2003\c_0321.doc