



The State of Utah
 Department of
 Natural Resources
 Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:		
Company	Mike W. Glasson	Environmental Coordinator
OGM	Karl Houskeeper	Environmental Scientist III

Inspection Report

Permit Number:	C0070019
Inspection Type:	COMPLETE
Inspection Date:	Monday, February 23, 2004
Start Date/Time:	02/23/2004 10:00:00 AM
End Date/Time:	02/23/2004 1:00:00 PM
Last Inspection:	Friday, January 23, 2004

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Storming ~Temp 35 Deg. F

InspectionID Report Number: 180

Accepted by: pgrubaug
 02/24/2004

Permittee: **ANDALEX RESOURCES INC TOWER DIVISION**

Operator: **ANDALEX RESOURCES INC TOWER DIVISION**

Site: **CENTENNIAL MINE**

Address: **PO BOX 902, PRICE UT 84501**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **INACTIVE**

Current Acreages

5,419.49	Total Permitted
35.27	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: _____

Date Monday, February 23, 2004

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!
Where ideas connect™

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
 - a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
 - b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit was re-issued effective 05/24/2002, to include the Mathis Tract, and expires 01/06/2007.

- Certificate of Insurance issued 07/01/2003 and terminates 07/01/2004.
- Reclamation agreement dated and signed February 1990 (amended January 2001).
- UPDES permit UTG040008 effective 05/01/2003 and expires midnight 04/30/2008.
- Air Quality permit DAQE-997-96, issued October 25, 1996.
- SPCC Plan dated 08/29/2003.

2. Signs and Markers

The mine permit ID sign located at the contact point of the public access to the permit area contained the required information. Other signs and markers observed during the inspection met the coal rules.

4.a Hydrologic Balance: Diversions

Notice of Violation NO. N04-49-2-1 abatement time was extended from February 23, 2004 to March 23, 2004. The abatement time was extended because of a request by the operator identifying frozen sediment and several attempts to clean the diversion. The last attempt was made on February 20, 2004. Since that date, the mine site has received another storm with approximately another six inches of snow. All diversions at the mine site are snow covered. Snow removal activities on roads and pads was taking place at the time of the inspection.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The fourth quarter and annual sediment pond inspections were done on 10/23/03. The inspections were conducted and certified by a P.E. The sediment capacity information from this inspection is as follows:

- Sediment Basin B, 0.119 acre feet remaining.
- Sediment Pond C, 0.225 acre feet remaining.
- Sediment Pond E, 1.435 acre feet remaining.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2003 water monitoring information was not available on site during the inspection. Water monitoring is performed by a contractor. Third quarter 2003 information was reviewed prior to and during the inspection. Third quarter 2003 water monitoring information is in the EDI website. The third quarter 2003 missing samples report was received on 01/02/2004. This report is generated from information contained in the EDI website. The report did not show any missing samples or parameters for third quarter 2003.

4.e Hydrologic Balance: Effluent Limitations

The discharge monitoring reports for January 2004 showed that 001, 002, 003, and 004 outfalls did not discharge.

14. Subsidence Control

Reviewed a letter from Bruce Ware, RLS. Mr. Ware stated in his letter dated October 19, 2003 that no horizontal or vertical movement has occurred at the listed sites in his report since they were established. Mr. Ware signed dated and certified this report with his RLS stamp.

20. Air Quality Permit

The air quality permit DAQE-997-96 referenced above remains in effect.

21. Bonding and Insurance

The insurance referenced in item #1 above is through Federal Insurance Company, policy #37102594. The insurance has explosion coverage, meets the minimum coverage requirements, lists the Division as the certificate holder, and has the proper language on the notification policy.

Bond No. SU34593 is for \$381,839 and Bond No.SU1354086 is for \$699,000. Both bonds remain in effect for the term of the permit and are through Utica Mutual Insurance Company.