



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Table with 2 columns: Role, Name. Title: Representatives Present During the Inspection. Rows: Company (Mike W. Glasson, Environmental Coordinator), OSM (Henry Austin), OGM (Karl Houskeeper, Environmental Scientist III)

Inspection Report

Table with 2 columns: Field, Value. Fields: Permit Number (C0070019), Inspection Type (COMPLETE OVERSITE), Inspection Date (Tuesday, May 09, 2006), Start Date/Time (5/9/2006 9:00:00 AM), End Date/Time (5/9/2006 4:00:00 PM), Last Inspection (Friday, April 21, 2006)

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Sunny, Temp 64 Deg. F.

InspectionID Report Number: 946

Accepted by: pgrubaug
5/16/2006

Permittee: ANDALEX RESOURCES INC TOWER DIVISION
Operator: ANDALEX RESOURCES INC TOWER DIVISION
Site: CENTENNIAL MINE
Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501
County: CARBON
Permit Type: PERMANENT COAL PROGRAM
Permit Status: ACTIVE

Current Acreages

Table with 2 columns: Value, Description. Rows: 6,602.02 Total Permitted, 35.27 Total Disturbed, Phase I, Phase II, Phase III

Mineral Ownership

- Checked: Federal, State, Fee
Unchecked: County, Other

Types of Operations

- Checked: Underground
Unchecked: Surface, Loadout, Processing, Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site.

Inspector's Signature:

Date: Tuesday, May 09, 2006

Karl Houskeeper, Environmental Scientist III
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site.

The current DOGM permit was re-issued effective 09/09/2004, to include the incidental boundary change in the Summit Tract, and expires 01/06/2007.

- Certificate of Insurance issued 07/01/2005 and terminates 07/01/2006.
- Reclamation agreement dated and signed February 1990 (amended January 2001).
- UPDES permit UTG040008 effective 05/01/2003 and expires midnight 04/30/2008.
- Air Quality permit DAQE-997-96, issued October 25, 1996.
- SPCC Plan dated 08/29/2003.

2. Signs and Markers

The mine permit ID sign located at the contact point of the public access to the permit area contained the required information. Other signs and markers observed during the inspection met the coal rules.

3. Topsoil

The topsoil pile above on the hillside above sediment pond C needs to have the topsoil pile sign re-installed on the fence post.

4.e Hydrologic Balance: Effluent Limitations

The discharge monitoring point 004 exceeded the designated parameter for loading on the March 2006 DMR. The point has experienced increased flows and not a rise in TDS. This location has exceeded this parameter for the last several months. The Department of Environmental Quality (DEQ) is aware of the problem and has been notified. DEQ is evaluating the issuance of a site specific permit to address this issue instead of the current general permit.

5. Explosives

The cap and explosive magazines were viewed as part of the complete oversight inspection. The magazines appeared to be properly installed and signs were placed to identify their location.

18. Support Facilities, Utility Installations

As part of the complete oversight inspection, several Gob Vent Holes (GVH) were viewed. GVH #3, #7, & #5 were viewed. Currently, there are five (5) holes installed, there are four (4) more holes approved to be constructed and drilled. Partial reclamation has been done on the five existing holes. The pad site for GVH #7 has been opened and the drillers were mobilizing during the inspection.

20. Air Quality Permit

The air quality permit DAQE-997-96 referenced above was issued on October 25, 1996 and remains in effect.

21. Bonding and Insurance

The insurance referenced in item #1 above is through Federal Insurance Company, policy #37102594. The insurance has explosion coverage, meets the minimum coverage requirements, lists the Division as the certificate holder, and has the proper language on the notification policy.

Bond No. SU34593 is for \$381,839 and Bond No. SU1354086 is for \$699,000. Both bonds remain in effect for the term of the permit and are through Utica Mutual Insurance Company.