0028

Inspection Report

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:		
Company	David Shaver	Manager
OGM	Karl Houskeeper	Environmental Scientist III

Permit Number:	C0070019
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, September 16, 2009
Start Date/Time:	9/16/2009 9:00:00 AM
End Date/Time:	9/16/2009 12:00:00 PM
Last Inspection:	Monday, August 17, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 76 Deg. F.

InspectionID Report Number: 2134

Accepted by: jhelfric
9/21/2009

Permitee: **ANDALEX RESOURCES INC TOWER DIVISION**
Operator: **ANDALEX RESOURCES INC TOWER DIVISION**
Site: **CENTENNIAL MINE**
Address: **6750 AIRPORT RD, PO BOX 902 PRICE UT 84501**
County: **CARBON**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

6,528.83	Total Permitted
47.19	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- [x] Federal
- [x] State
- [ ] County
- [x] Fee
- [ ] Other

Types of Operations

- [x] Underground
- [ ] Surface
- [ ] Loadout
- [ ] Processing
- [ ] Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: Karl R. Houskeeper **Date** Wednesday, September 16, 2009

Karl Houskeeper, Environmental Scientist III
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • *www.ogm.utah.gov*

Permit Number: C0070019
Inspection Type: PARTIAL
Inspection Date: Wednesday, September 16, 2009

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☐	☐	☐	☐
4.a Hydrologic Balance: Diversions	☐	☐	☐	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☑	☐	☑	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☐	☐	☐	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☑	☐	☑	☐
5. Explosives	☑	☐	☑	☐
6. Disposal of Excess Spoil, Fills, Benches	☑	☑	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☑	☑	☐	☐
8. Noncoal Waste	☑	☐	☑	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10. Slides and Other Damage	☐	☐	☐	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☐	☐	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b Roads: Drainage Controls	☐	☐	☐	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☐	☐	☐	☐
19. AVS Check	☐	☐	☐	☐
20. Air Quality Permit	☐	☐	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☐	☐	☐	☐

2. Signs and Markers

The mine permit ID signs are located at the contact points of public access to the permit area.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Recent rain storms has placed standing water in the bottoms of the sediment ponds.

4.e Hydrologic Balance: Effluent Limitations

Mine sealed. No mine water discharge. No discharge form any of the surface locations.

5. Explosives

Only one magazine remains on site. The other magazine has been removed.

8. Noncoal Waste

Area free of noncoal waste items.