

*Outgoing*  
0070019

## Suzanne Steab - April 2011 Inspection Reports

---

*K*

**From:** Karl Houskeeper  
**To:** dshaver@coalsource.com  
**Date:** 5/4/2011 3:16 PM  
**Subject:** April 2011 Inspection Reports  
**CC:** ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov  
**Attachments:** Crandall April 2011.pdf; Centennial April 2011.pdf

---

Dave,

Attached is the April 2011 inspection reports for Crandall and Centennial.

Thanks,  
Karl



**State of Utah**  
DEPARTMENT OF NATURAL RESOURCES

**MICHAEL R. STYLER**  
Executive Director

**Division of Oil, Gas and Mining**

**JOHN R. BAZA**  
Division Director

**Inspection Report**

Permit Number:	C0070019
Inspection Type:	PARTIAL
Inspection Date:	Monday, April 18, 2011
Start Date/Time:	4/18/2011 8:30:00 AM
End Date/Time:	4/18/2011 12:00:00 PM
Last Inspection:	Wednesday, March 09, 2011

Representatives Present During the Inspection:	
Company	Dave Shaver
OGM	Karl Houskeeper

Inspector: Karl Houskeeper

Weather: Overcast, Temp. 55 Deg. F.

Inspection ID Report Number: 2715

Accepted by: jhefric  
5/3/2011

Permittee: **ANDALEX RESOURCES INC**  
Operator: **ANDALEX RESOURCES INC**  
Site: **CENTENNIAL MINE**  
Address: **PO BOX 910, EAST CARBON UT 84520-0910**  
County: **CARBON**  
Permit Type: **PERMANENT COAL PROGRAM**  
Permit Status: **ACTIVE**

Current Acreages		Mineral Ownership	Types of Operations
6,528.83	Total Permitted	<input checked="" type="checkbox"/> Federal	<input checked="" type="checkbox"/> Underground
47.19	Total Disturbed	<input checked="" type="checkbox"/> State	<input type="checkbox"/> Surface
	Phase I	<input type="checkbox"/> County	<input type="checkbox"/> Loadout
	Phase II	<input checked="" type="checkbox"/> Fee	<input type="checkbox"/> Processing
	Phase III	<input type="checkbox"/> Other	<input type="checkbox"/> Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: \_\_\_\_\_

*Karl Houskeeper*

Date: Monday, April 18, 2011

Karl Houskeeper,  
Inspector ID Number: 49

Note: This inspection report does not constitute an O&G permit. It is a compliance report for the regular program of the Division of Oil, Gas and Mining.  
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



Permit Number: C0070019  
 Inspection Type: PARTIAL  
 Inspection Date: Monday, April 18, 2011

**Inspection Continuation Sheet**

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit Number: C0070019  
Inspection Type: PARTIAL  
Inspection Date: Monday, April 18, 2011

**Inspection Continuation Sheet**

*Page 3 of 3*

**2. Signs and Markers**

Mine identification sign in place at a point of public access into the permit area. The sign contains the required information.

**4.a Hydrologic Balance: Diversions**

The tree that traversed the upper main road diversion has been removed.

**5. Explosives**

Only the cap magazine remains on site. The explosive magazine has been removed.