



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070019
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, February 25, 2020
Start Date/Time:	2/25/2020 8:00:00 AM
End Date/Time:	2/25/2020 11:00:00 PM
Last Inspection:	Tuesday, November 26, 2019

Representatives Present During the Inspection:	
Company	Karin Madsen
OGM	Karl Houskeeper

Inspector: Karl Houskeeper

Weather: Clear Skies, Temp 32 Deg. F.

InspectionID Report Number: 6629

Accepted by: SCHRISTE
3/2/2020

Permitee: **ANDALEX RESOURCES INC**
 Operator: **ANDALEX RESOURCES INC**
 Site: **CENTENNIAL MINE**
 Address: **PO BOX 910, EAST CARBON UT 84520-0910**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **INACTIVE**

Current Acreages

2,274.77	Total Permitted
47.19	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Entire site is snow covered. Limited access is available along the main roadways. All side areas are unplowed and inaccessible.

Karl R. Houskeeper

Inspector's Signature:

Date: Tuesday, February 25, 2020

Karl Houskeeper,
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit was issued effective 01/04/2017 and expires on 01/04/2022.

- Certificate of Insurance issued 06/01/2019 and terminates 06/01/2020.
- Reclamation agreement dated and signed 23 July 2018.
- UPDES permit UTG040029 effective 04/01/2019 and expires midnight 03/31/2024.
- Air Quality permit DAQE-997-96, issued October 25, 1996, modified November 16, 2003.
- SPCC Plan re-certified 02/28/2019

2. Signs and Markers

The mine identification sign was observed at the main entrance. The name, address, phone number and mining permit number are listed on the signs. Both signs are identical and contained the required information set forth in the Utah R645 Coal Rules. The sign is in compliance.

4.a Hydrologic Balance: Diversions

Diversions are all snow covered. They will need to be evaluated in the spring after snow melt.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

First quarter 2020 sediment pond inspections were done on 01/07/2020. No problems noted.

4.e Hydrologic Balance: Effluent Limitations

No discharges have occurred. Reports are submitted to DEQ electronically.

5. Explosives

No explosives are on site.

7. Coal Mine Waste, Refuse Piles, Impoundments

There is no refuse pile associated with this mine site.

14. Subsidence Control

No active mining.

16.a Roads: Construction, Maintenance, Surfacing

Roadways are all snow covered except a portion of the main access road.

20. Air Quality Permit

DAQE-997-96 issued October 25, 1996 and modified November 16, 2003.

Permit Number: C0070019
Inspection Type: COMPLETE
Inspection Date: Tuesday, February 25, 2020

21. Bonding and Insurance

Bond is \$1,152,000.

ANDALEX RESOURCES INC. (PERMITTEE) A SUBSIDIARY OF-

UtahAmerican Energy Inc.

P.O. BOX 910
EAST CARBON, UT 84520

(435) 888-4000

PERMIT # C 007/019

First Sign located on Main Access to Centennial Mine



Overview Of The Centennial Mine



**NOTICE
PRIVATE PROPERTY**
THIS PROPERTY
IS PROTECTED BY
ELECTRONIC SURVEILLANCE.

UtahAmerican
Energy Inc.
U000W PERMIT BOUNDARY
PERMIT # C 0071019

Access Gate To The Centennial Mine