Suzanne Steab - January 2011 Inspection Report

From: Karl Houskeeper
To: kit@emerytelcom.net
Date: 2/3/2011 12:27 PM
Subject: January 2011 Inspection Report
CC: ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov
Attachments: Horizon January 2011.pdf

Kit,

Attached is the January 2011 inspection report for Horizon.

Thanks,
Karl

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

Inspection Report

Permit Number:	C0070020
Inspection Type:	PARTIAL
Inspection Date:	Thursday, January 13, 2011
Start Date/Time:	1/13/2011 9:30:00 AM
End Date/Time:	1/13/2011 1:30:00 AM
Last Inspection:	Thursday, December 09, 2010

Inspector: Karl Houskeeper,

Weather: Clear, Temp. 15 Deg. F.

InspectionID Report Number: 2616

Accepted by: jhelfric
1/26/2011

Representatives Present During the Inspection:	
Company	Kit Pappas
OGM	Karl Houskeeper

Permitee: **HIDDEN SPLENDOR RESOURCES**
Operator: **HIDDEN SPLENDOR RESOURCES**
Site: **HORIZON MINE**
Address: **57 WEST 200 SOUTH, SUITE 400, SALT LAKE CITY UT 84101**
County: **CARBON**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

1,577.00	**Total Permitted**
9.50	**Total Disturbed**
	Phase I
	Phase II
	Phase III

Mineral Ownership

- [x] Federal
- [ ] State
- [ ] County
- [x] Fee
- [ ] Other

Types of Operations

- [x] Underground
- [ ] Surface
- [ ] Loadout
- [ ] Processing
- [ ] Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: Karl R. Houskeeper **Date** Thursday, January 13, 2011

Karl Houskeeper,
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

UTAH DNR OIL, GAS & MINING

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2. Signs and Markers	✔	☐	✔	☐
3. Topsoil	☐	☐	☐	☐
4.a Hydrologic Balance: Diversions	✔	☐	✔	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☐	☐	☐	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☐	☐	☐	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5. Explosives	✔	☐	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	✔	✔	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	✔	✔	☐	☐
8. Noncoal Waste	✔	☐	☐	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10. Slides and Other Damage	☐	☐	☐	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☐	☐	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b Roads: Drainage Controls	☐	☐	☐	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☐	☐	☐	☐
19. AVS Check	☐	☐	☐	☐
20. Air Quality Permit	☐	☐	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☐	☐	☐	☐

2. Signs and Markers

Observed the mine identification sign at a point of public access into the permit area. The sign contained the required information.

4.a Hydrologic Balance: Diversions

The diversion adjacent to the office/bath house has snow pushed into it. Arrangements were made to remove the snow from the diversion during the inspection.