



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070020
Inspection Type:	COMPLETE
Inspection Date:	Thursday, May 23, 2013
Start Date/Time:	5/23/2013 9:30:00 AM
End Date/Time:	5/23/2013 1:00:00 PM
Last Inspection:	Thursday, April 18, 2013

Representatives Present During the Inspection:	
Company	Kit Pappas
OGM	Karl Houskeeper

Inspector: Karl Houskeeper

Weather: Clear Skies, Temp. 68 Deg. F.

InspectionID Report Number: 3485

Accepted by: jhelfric

5/23/2013

Permittee: **HIDDEN SPLENDOR RESOURCES**
 Operator: **HIDDEN SPLENDOR RESOURCES**
 Site: **HORIZON MINE**
 Address: **57 WEST 200 SOUTH, SUITE 400, SALT LAKE CITY UT 84101**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

1,577.00	Total Permitted
9.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The mine remains idle.

Karl R. Houskeeper

Inspector's Signature:

Date Thursday, May 23, 2013

Karl Houskeeper,
Inspector ID Number: 49



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/007/020 was issued effective 10/11/2011 and expires 10/11/2016.

-Certificate of Insurance certificate #4413805 issued 06/04/2012 and terminates 06/04/2013.

-UPDES permit UTG040000 (General) UTG040019 (Site Specific) effective 05/01/2008 and expires midnight 04/30/2013. (under temporary extension)

-Air Quality permit DAQE-700-70, issued November 7, 2000.

-SPCC Plan dated January 2010. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

2. Signs and Markers

The mine identification sign is found along side of the Carbon County road used to access the Mine Site and prior to entrance into the Mine Permit area. The sign contains the required information set forth in the Utah R645 Coal Rules. The sign is in compliance with the regulations.

3. Topsoil

A topsoil pile sign located on the topsoil pile below the sediment pond has slid down the pole to the ground and is not visible. This items was discussed with mine personnel on site to arrange for the sign to be re-secured so that is visible.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

First quarter 2013 sediment pond inspection was done on February 15, 2013. No problems were noted in this sediment pond inspection.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the April 2013 discharge monitoring reports. No problems were noted.

8. Noncoal Waste

Items of noncoal waste were observed along side of and in the main diversion that is adjacent to the Office/bath house building. These items were discussed with mine personnel on site during the inspection to arrange for them to be gathered and disposed of properly.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-700-00 was issued on November 7, 2000. Recent documentation shows the approval order number as DAQP-002-06.

21. Bonding and Insurance

The bond is secured by a letter of credit through Bank One in the amount of \$57,000 and collateral to add up to the amount of \$342,000. This letter of credit expired on January 20, 2007. The appraisal was updated as of 12/20/06 for the real estate (collateral) and the appraisal is now \$625,000 and the collateral is adequate. The updated reclamation cost estimate is \$445,000 in 2011 dollars.