

ATTACHMENT A – Photos July 19, 2018 site visit



PHOTO 1

Asphalt removed from upper pad down to gate.



PHOTO 2

Dozer pushing coal waste pile onto lower pad.



PHOTO 3

Dozer pushing coal waste pile onto lower pad.



PHOTO 4

Concrete portal seals covered with dirt to help them cure evenly.

ATTACHMENT A – Photos July 19, 2018 July 20, 2018site visit



PHOTO 5
Beginning of channel excavation near fan portal.



PHOTO 6
Piles being placed and compacted near portals.



PHOTO 7
Backfilled portals.



PHOTO 8
Coal waste pushed in lifts onto lower pad.