

ATTACHMENT A – Photos August 29, 2018 site visit



PHOTO 1 – Looking southeast to the sediment pond. Once Jewkes creek is built, this will be the location of the confluence of Portal and Jewkes creeks.



PHOTO 2 – Looking northwest at the finished channel and reclaim slopes in Portal canyon. Excavator applying finishing touches.



PHOTO 3 – A wider view of the finished Portal canyon channel in Photo 2. Boulder salvage pile to the right of center.



PHOTO 4 – A muddy, messy sediment pond. This pump was previously set up to get rid of the excess water. It was not in operation during this time.

ATTACHMENT A – Photos August 29, 2018 site visit



PHOTO 5 – Pump discharge hose. It doesn't appear much was pumped from the pond.



PHOTO 6 – Small D6 Dozer spreading newly placed topsoil along the western reclaim slopes of Portal Canyon.



PHOTO 7 – Excavator loading topsoil into articulated haul truck to be spread on regraded slopes downcanyon.



PHOTO 8 – After being loaded, this haul truck will BACK UP all the way to the dump site where the small D6 Dozer is waiting.

ATTACHMENT A – Photos August 29, 2018 site visit



PHOTO 9 – Looking north from monitoring well HZ-95-3.



PHOTO 10 – Looking south from monitoring well HZ-95-3.



PHOTO 11 – Monitoring well HZ-95-3. The cap comes off to reveal this coiled up spool.



PHOTO 12 – Monitoring well HZ-95-3. A rock dropped into this pipe appears to make contact with fill about 5 feet down.

ATTACHMENT A – Photos August 29, 2018 site visit



PHOTO 13 – Haul truck dumping topsoil for awaiting D6 Dozer in Portal Canyon.



PHOTO 14 – D6 Dozer pushing topsoil in Portal Canyon.



PHOTO 15 – D8 Dozer pushing material away from Portal/Jewkes confluence.



PHOTO 16 – Another view of the sediment pond.

ATTACHMENT A – Photos August 29, 2018 site visit



PHOTO 17 – These logs/tree branches are stacked on this topsoil storage area in anticipation of later use as engineered log jams in reclaimed channels.



PHOTO 18 – Collapsed culverts and other scrap steel that will eventually be salvaged.

ATTACHMENT A – Photos August 29, 2018 site visit



PANORAMA 1 – Looking southwest over the county road, lower pad, and sediment pond.



PANORAMA 2 – Continuing the panorama from the photo above, this looks out across the entirety of Portal Canyon. Excavator finishing slopes on the left, and D6 pushing topsoil over reclaimed slopes on the right.

ATTACHMENT A – Photos August 29, 2018 site visit



PANORAMA 3 – Taken from a higher vantage point, this shows the topsoil spreading effort on the western slopes of Portal Canyon.



PANORAMA 4 – D6 Dozer pushing topsoil over reclaimed slopes on the left. Excavator and articulated haul truck harvesting topsoil on the right.