

ATTACHMENT A – Photos Date site visit



PHOTO 1

Artic truck hauling topsoil to placement area.



PHOTO 2

Excavator loading artic truck with topsoil.



PHOTO 3

Temporary topsoil haul road.



PHOTO 4

Dozer pushing topsoil into place on slopes.

ATTACHMENT A – Photos Date site visit



PHOTO 5
Lower pad staging area.



PHOTO 6
Excavator working on edge of pond where it is dry.



PHOTO 7
Topsoil being salvaged from pile in Portal Canyon.



PHOTO 8
From topsoil pile looking down Portal Canyon.