



**ATTACHMENT A – Photos Date site visit**



**PHOTO 1**

Inlet to Jewkes reconstructed channel



**PHOTO 2**

Jewkes creek excavation



**PHOTO 3**

Jewkes creek excavation



**PHOTO 4**

Jewkes creek excavation

**ATTACHMENT A – Photos Date site visit**



**PHOTO 5**

Hauling topsoil down to lower pile



**PHOTO 6**

Portal canyon topsoiled



**PHOTO 7**

Jewkes channel excavation



**PHOTO 8**

Base of removed power pole on hillslope near pre-law portal