

12-22-88 7020

0001



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John SLL

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: December 14, 1988
3 p.m. to 5 p.m.

Permittee and/or Operators Name: North American Equities (NAE) (415)866-7186
Operator's Repr.: William Prince; Holme, Robert & Owen (801)521-5800
Business Address: 50 S. Main Street, Salt Lake City, UT 84114
Mine Name: Blazon #1 Mine Permit Number: INA/007/021
Type of Mining Activity: Underground XX Surface Other
County: Carbon
Company Official (s): None
State Official(s): Harold G. Sandbeck
Partial: XX Complete: Date of Last Inspection: November 17, 1988
Weather Conditions: Cloudy and cold
Acreage: Permitted 320 Disturbed 1.5 Regraded Seeded Bonded 1.5
Enforcement Action:

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(XX)	()	()	(XX)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	(XX)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(XX)	()	()	(XX)
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION 12/14/88

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. The site was inaccessible. The road leading into the reclaimed site was covered with 2 to 3 feet of snow.

1. Permits.

Certificate of Insurance

The Division received a valid copy of the renewed insurance policy. The policy expires on October 23, 1989. The new policy number is MXC 801 333 11.

Bond

The operator was informed that the bond expires on January 31, 1989.

Stipulations

The Division letter dated November 30, 1988 titled "Request for Bond Release" required the operator to address the outstanding stipulations within 45 days of the receipt of the above mentioned letter.

4. Hydrologic Balance:

c. Sediment Ponds and Impoundments. The operator was informed that a 1988 4th quarter pond inspection is required. For more information, the reader is referred to the November 17, 1988 inspection report.

e. Surface and Groundwater Monitoring.

As mentioned in the November 17, 1988 inspection report, the June 1988 field water data had not been submitted with the lab analysis. This field data was received by the Division on December 5, 1988. No problems were noted.

On November 23, 1988, the Division received the weekly water data analysis taken during the reclamation activity. Samples were collected beginning September 9, 1988 through November 3, 1988. The results were inspected and no problems were noted.

Copy of this Report:

Mailed to: Mr. William Prince (Holme, Robert & Owen), Price Office and

Mailed to: Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Hawel J. J.* #27 Date: 12/21/88