



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Jan

gh sa

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 3/22/88
8:45 am to 9:45 am

Permittee and/or Operators Name: North American Equities (NAE)(415)866-7186
Business Address: 3160 Crow Canyon Road, Suite 210, San Ramon, CA 94583
Mine Name: Blazon #1 Mine Permit Number: INA/007/021
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): None
State Official(s): Randy Harden, Kent Wheeler
Partial: Complete: Date of Last Inspection: February 24, 1988
Weather Conditions: Clear, snowpack
Acreage: Permitted 320 Disturbed 1.5 Regraded Seeded Bonded 1.5
Enforcement Action: _____

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/007/021

DATE OF INSPECTION 3/22/88

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits.

Currently the site is inaccessible by vehicles due to winter conditions and snow cover. Access was made to the site via foot travel. No activity has occurred at the site. Conditions observable at the site were limited due to approximately 3 feet of snow cover. No apparent concerns were noted.

Copy of this Report:

Mailed to: Mr. Alan Smith - NAE, John Kathman-OSM

Given to: Joe Helfrich, Susan Linner-DOGM

Inspectors Signature and Number: #13



Date: March 29, 1988