



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: January 29, 1988
12:00 pm to 1:00 pm

Permittee and/or Operators Name: North American Equities (NAE)(415)866-7186
Business Address: 3160 Crow Canyon Road, Suite 210, San Ramon, CA 94583
Mine Name: Blazon #1 Mine Permit Number: INA/007/021
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): _____
State Official(s): Randy Harden & Darron Haddock
Partial: Complete: Date of Last Inspection: December 9, 1987
Weather Conditions: Cool, approximately 3' of snow on ground
Acreage: Permitted 320 Disturbed 1.5 Regraded Seeded Bonded 1.5
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	(X)	()	()	(X)
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/007/021

DATE OF INSPECTION January 29, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS

The sign at the entrance to the mine site has been replaced in accordance with part 1 of C87-15-2-1 issued on December 4, 1987.


15. CESSATION OF OPERATIONS

Due to freezing ground conditions and snow cover, no reclamation activity on the site is currently being conducted. There is no evidence of any site activity on the property. The site is inaccessible to equipment and vehicles. The inspection had to be accomplished by walking to the site approximately 1 mile. Deep snow on the site prevented complete coverage of the facilities.

Copy of this Report:

Mailed to: John Kathman - OSM Mr. Alan Smith - NAE

Given to: Joe Helfrich - DOGM

Inspectors Signature and Number: #13  Date: February 3, 1988

NORTH AMERICAN EQUITIES LTD.

4898

DATE	DESCRIPTION	AMOUNT	DEDUCTION	NET AMOUNT
1/15/88	Violation #N87-15-1-1	\$309.90		\$309.90

CHECK DATE	CONTROL NUMBER	TOTALS	
1/15/88	4898		\$309.90

NORTH AMERICAN EQUITIES, LTD.

1401 - 17TH ST., SUITE 1600
DENVER, CO 80202

DOMINION NATIONAL BANK
DENVER, COLORADO 80202
23-391/1020

4898

****THREE HUNDRED NINE DOLLARS & 90/100*****

PAY
TO THE
ORDER OF

State of Utah
Natural Resources
Division of Oil, Gas & Mining
355 W. North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180

DATE	CONTROL NO.	AMOUNT
1/15/88	4898	\$309.90

Jill R. Stahl

⑈004898⑈ ⑆102003918⑆ 21 04474⑈

IWA/007/021