0001

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/007/021

Inspection Date December 5, 1989

Permittee/Operator Name North American Equities (NAE) (415)866-7186

Business Address 50 S. Main Street

City Salt Lake City State Utah Zip 84114

Mine Blazon #1 Mine ☐ Surface ☒ Underground ☐ Other

County Carbon State Utah

Company Official(s) No one

State Official(s) Harold G. Sandbeck

Time of inspection 4:00 ☐ a.m. ☒ p.m. to 5:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection November 14, 1989 Weather conditions Clear and Cold

Acreage 320 ☒ Permitted 1.5 ☒ Disturbed ☐ Regraded ☐ Seeded 1.5 ☒ Bonded

Enforcement Action Pending Violations: N89-31-03-01 and N89-17-02-01 (See 2nd Page)

Operator's Repr.: William Prince; Holme, Roberts & Owen (801) 521-5800

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/007/021

Inspection Date December 5, 1989

Please number comments to correspond with topics on previous page.

General Comments: The operator was unavailable to accompany the undersigned inspector on this complete inspection. Snow cover was in excess of 18 inches.

1. Permits:

Bond

The renewed letter of credit was received by the Division on May 30, 1989. The bond expires on December 31, 1989.

Insurance

The operator's insurance expires on November 22, 1990.

2. Signs and Markers:

The mine site and its access road were covered with snow in excess of 18 inches. The undersigned inspector walked to the main gate and found no evidence of recent activity on the mine site.

Copy of report mailed to Mr. William Prince (Holme, Roberts & Owen), Rice Office, Brian Smith (OSM) and Carol Bjork (Earthfax Engineering, Inc.)

Copy of report given to Sue Linner and Joe Helfrich – DOGM

Inspector's signature Howard D. Sandberg No. #27

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/007/021

Inspection Date December 5, 1989

Please number comments to correspond with topics on previous page.

Violation Status

N89-31-03-01: Terminated November 16, 1989. See attachment for additional information.

N89-17-02-01: Terminated November 16, 1989. See attachment for additional information.

Copy of report mailed to Mr. William Prince (Holme, Roberts & Owen), Price Office, Brian Smith (OSM) and Carol Bjork (Earth Fax Engineering, Inc.)

Copy of report given to Sue Linner and Joe Helfrich — DOGM

Inspector's signature Howard D. Sandbach No. 27

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

an equal opportunity employer