



NO. N89-17-2-1

notice of violation

To the following Permittee or Operator:

Name North American Equities

Mine Blazon #1 Mine  Surface  Underground  Other

County Carbon State Utah Telephone 521-5800

Mailing Address Holme, Roberts & Owen, 50 South Main Street, Salt Lake City, Utah, 84144

State Permit No. ACT/007/021

Ownership Category  State  Federal  Fee  Mixed

Date of inspection November 2, 19 89

Time of inspection 2:00  a.m.  p.m. to 3:00  a.m.  p.m.

Operator Name (other than Permittee) \_\_\_\_\_

Mailing Address \_\_\_\_\_

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  **is not**  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing November 3, 1989

Time of service/ mailing 10:00  a.m.  p.m.

William Prince, Esq.  
Permittee/Operator representative

\_\_\_\_\_  
Title

Signature

Lynn Kunzler  
Division of Oil, Gas & Mining representative

Reclamation Biologist  
Title

Lynn M Kyl  
Signature

#17  
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



**NOTICE OF VIOLATION NO. N 89-17-2-1**

Violation No. 1 of 1

Nature of violation

Failure to conduct reclamation activities in accordance with approved plan and failure to perform revegetation activities in a timely manner.

Provisions of act, regulations or permit violated

UMC 71.19, UMC 817.111(b), UMC 817.113, UMC 817.114

Portion of operation to which notice applies

North side of Little Snyder drainage, cut slope above pad, slide area on Portal slope, and spoil material on north side of Little Snyder.

Remedial action required (including any interim steps)

1. Cover spoil material with 6" of suitable plant growth material (Topsoil),
2. Seed and mulch areas identified in accordance with approved plan,
3. install netting to anchor mulch in Little Snyder drainage.

Abatement time (including interim steps)

By November 10, 1989 at 5:00PM.