



NO. N 89-31-3-1

notice of violation

To the following Permittee or Operator:

Name NORTH AMERICAN EQUITIES, LTD.

Mine BLAZON NO. 1 (RECLAIMED) Surface Underground Other

County CARBON State UTAH Telephone _____

Mailing Address 50 S. MAIN SUITE 900, SALT LAKE CITY, UT 84114

State Permit No. ACT/007/021

Ownership Category State Federal Fee Mixed

Date of inspection OCTOBER 12, 19 89

Time of inspection 9:00 a.m. p.m. to 1:00 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling 10/13/89

Time of service/mailling 3:00 a.m. p.m.

WILLIAM PRINCE
Permittee/Operator representative

ATTORNEY
Title

MAILED FROM D.O.G.M. OFFICE
Signature

MIKE DeWEESE
Division of Oil, Gas & Mining representative

RECLAMATION HYDROLOGIST
Title

Michael M. De Ware
Signature

#31
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 89-31-3-1

Violation No. 1 of 1

Nature of violation

FAILURE TO MAINTAIN APPROPRIATE SEDIMENT CONTROL MEASURES

Provisions of act, regulations or permit violated

UMC 817.45

Portion of operation to which notice applies

THE SILT FENCE STRUCTURE EXTENDING FROM THE NORTH PORTION OF THE BACKFILLED HIGHWALL TO THE SOUTH END OF THE PROPERTY.

Remedial action required (including any interim steps)

RECONSTRUCT SILT FENCE TO A FUNCTIONAL CONDITION.

Abatement time (including interim steps)

NO LATER THAN 5:00 P.M. ON MONDAY, NOVEMBER 13, 1989.